

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

P.O. BOX 1980
HORRIS, NEW MEXICO 88240

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

Texaco E&P, Inc.

3. Address and Telephone No.

P. O. Box 3109 - Midland, TX 79702

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Unit P 330' FSL; 330' FEL Sec 20 T-25S R-32E

5. Lease Designation and Serial No.

LC-062300 LC-06/869

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

Unit P

8. Well Name and No.

Cotton Draw Unit #43

9. API Well No.

30-025-08202

10. Field and Pool, or Exploratory Area

Paduca Delaware

11. County or Parish, State

Lea, NM

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☒ Notice of Intent
☐ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☒ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☐ Other

- ☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

1. Notify BLM prior to plugging and abandonment of well.
2. TIH w/tubing tag CIBP @ 4556'. Circulate casing w/25# per bbl. salt gel mud.
3. Spot 40 sx cmt plug f/4556'-4256'.
4. Perf. & Sqz. 85 sx cment @ 1170' w/pkr @ 1000' (top of salt 1122').
5. Spot 25 sx cmt plug f/775'-675' (Rustler 725').
6. Perf 4 1/2" casing @ 430' & circ. cement to surface behind casing. Lease casing full of cement from 430' to surface @ 150 sx cmt.
7. Nipple down BOP & cut off wellhead; cap well & install dry hole marker.

RECEIVED
MAY 16 10 55 AM '95
S&P
ARL

14. I hereby certify that the foregoing is true and correct

Signed RJ Hand

Title Operations Engineer

Date 5/16/95

(This space for Federal or State office use)

Orig. Signed by Shannon J. Shaw

Title HYDROFUM ENGINEER

Date 6/30/95

Approved by
Conditions of approval, if any:

RECEIVED
JUL 06 1995
OCD HOELS
OFFICE