

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.	3002508203
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil / Gas Lease No.	145870
7. Lease Name or Unit Agreement Name	COTTON DRAW UNIT
8. Well No.	25
9. Pool Name or Wildcat	PADUCA DELAWARE
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

SUNDRY NOTICES AND REPORTS ON WELL (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well:	OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator	TEXACO EXPLORATION & PRODUCTION INC.
3. Address of Operator	205 E. Bender, HOBBS, NM 88240
4. Well Location	Unit Letter <u>A</u> : <u>660</u> Feet From The <u>NORTH</u> Line and <u>660</u> Feet From The <u>EAST</u> Line Section <u>21</u> Township <u>25S</u> Range <u>32E</u> NMPM <u>LEA</u> COUNTY
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐
COMMENCE DRILLING OPERATION ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

4-01-98: MIRU. PMP STUCK. WRKD LOOSE. INSTL BOP. TAG FILL @ 4698'. PULL 2 3/8" TBG.
4-02-98: RAN BIT & BAILER ON 2 3/8" TBG. C/O FR 4698-4716' (JUNK).
4-03-98: WELLCHECK 2 3/8" TBG. RAN TP, PKR, SN & TBG TO 4660'. SPOT 250 GALS TOLUENE OVER PERFS. PSA 4558'.
4-06-98: TBG PRESS-0 PSI. FSH SPOT CONTROL VALVE. SWAB DN FLOWLINE. FL @ 800'. END FL @ 2500'. REL PKR. RESET PKR @ 4465'. TP @ 4558'. ACIDIZED 4618-4659' W/3500 GALS 7.5% 60:40 DAD IN 3 STGS. FLSH W/20 BBLs 2% KCL FW.
4-07-98: REL PKR. RAN BIT & BAILER. C/O FR 4678-4716'. RECD FORMATION SAND & SALT. RAN MA, SN, 2 3/8" TBG, & TA. REM BOP. MA @ 4705'. SN @ 4687'. TA @ 4562'.
4-08-98: RAN RODS. RAN GAS ANCHOR ON PMP, BACKOFF TOOL, SNKR BARS, & RODS. DID NOT LOAD TBG. SPACE PMP @ 4". RIG DOWN. ON PRODUCTION @ 5:00 PM. PMPNG & TESTING.
4-13-98: WELL NOT PUMPING. MIRU. LONG STROKE PUMP. ON VAC. PULL RDS & PMP. PMP PLUNGER STUCK. TAG FILL @ 4716'. BTM OF TBG @ 4705'. SN @ 4686'. TA @ 4562'.
4-14-98: RAN GAS ANCHOR, PMP, BACKOFF TOOL, SNKR BARS, & RODS. LOAD TBG W/10 BBLs 2% KCL FW. SPACE PUMP @ 3". TEST TBG TO 500 PSI-OK. ON PRODUCTION @ 12 NOON. PUMPING & TESTING.
5-22-98: ON 24 HR OPT. PUMPED 14 BO, 203 BW, & 5 MCF.
FINAL REPORT

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. Denise Leake TITLE Engineering Assistant

DATE 6/3/98

TYPE OR PRINT NAME J. Denise Leake

Telephone No. 397-0405

(This space for State Use)

Orig. Signed by
Paul Kautz
Geologist

APPROVED BY _____ TITLE _____

DATE JUN 25 1998

CONDITIONS OF APPROVAL, IF ANY: