## Form approved, Budget Bureau No. 42-R1424. UNITE STATES SUBMIT IN TRIPLICA" DEPARTMENT THE INTERIOR (Other instructions on verse side) 6. LEASE DESIGNATION AND SERIAL NO GEOLOGICAL SURVEY LC-061869 6. IF INDIAN, ALLOTTEE OR TRIBE NAME SUNDRY NOTICES AND REPORTS ON WELLS om for proposals to drill or to deepen or plug back to a different reservoir. Se "APPLICATION FOR PERMIT—" for such proposals.) 7. UNIT AGREEMENT NAME 2. OTHER Cotton Draw Unit 8. FARM OR LEASE NAME Cotton Draw Unit 1 KACO Inc. i. Q. Box 728 Hobbs New Mexico 88240 The part of the state of the state requirements.\* The state of the sta 25 10. FIELD AND POOL, OR WILDCAT Well is located 660' from the Morth Line Paduca Delaware 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA - acc! from the East Line of Section 21, T-25-S, R-32-E, Lea .mij, hew lexico. Sec. 21, T-25-C, K-31-1 (Unit Letter A) A TEN NO 12. COUNTY OR PARISH 13. STATE 15. ELEVATIONS (Show whether DF, RT, GR, etc.) Lew Mexica 3429! (D.F.) .Kugular.. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PULL OR ALTER CASING WATER SHUT-OFF REPAIRING WELL ALTERING CASING FRACTURE TREATMENT X MULTIPLE COMPLETE JOSE TREAT SHOOTING OR ACIDIZING ABANDON MENT\* CHANGE PLANS (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form ) competion or recompletion report and log form.) and the constitution of the completion report and log form.) and the constitution of the completion report and log form.) and the constitution of the completion report and log form.) and the constitution of the completion report and log form.) The Following Work Has Been Completed On Subject Well rull 2 3/8" O.D. production rods & tabing. Sun 2 7/8" O. D. frac tubing w/backer and set @ 4668'. Spot 50 gals. 15% rel from 4640' to 4668'. rull tuping to 4592' and set packer. Pump remaining 500 gals. Mi acid hown thing. 5. Frac perforations w/20,000 gals. gelled lease crude containing 14 20/40 sand per gal. and 25# Adomite & 20# gelling agent per 1000 gal. Frac in 3 equal stages using 55# Unibeads after each stage. . Furl frac tubing & run 2 3/8" 0.D. production tubing. swab until flowing, test, and return to production.

and correspond is true and corre	ct Ausia	stant Distr	ict			
SPONED TO THE STATE OF THE SPONED	TITLE Super	intendent	APPRO	<b>VED</b> TE CC	tober 22	<u> </u>
Plus space for Federal or State office use)					•	
STEROVED BY	TITLE:		OCT 27	19 <b>68</b> ate		

J L GORDON Acting district engineer