

Form 3160-5
(June 1990)

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

Texaco E&P, Inc.

3. Address and Telephone No.

P. O. Box 3109 - Midland, TX 79702 915/688-4816

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Unit K 1980' FSL, 1980' FWL Sec. 21 T-25S R-32E

N. HOBSON'S COMMISSION
P.O. BOX 1000
HOBSON, NEW MEXICO 88240

Bureau No. 1004-0135

Expires: March 31, 1993

5. Lease Designation and Serial No.

LC-062300 LC 06869

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

Unit K

8. Well Name and No.

Cotton Draw Unit 29

9. API Well No.

30-025-08207

10. Field and Pool, or Exploratory Area

Paduca Delaware

11. County or Parish, State

Lea, NM

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☒ Notice of Intent
☐ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☒ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☐ Other

- ☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

1. Notify BLM prior to plugging and abandonment of well.
2. RU wireline & set cmt ret. @ 4520'. Sqz. 40 sx cmt into perfs. @ 4592'-4647'. Unsting from retainer & cap w/40 sx cmt. from 4520' - 4220'. (base of salt 4335').
3. Circ. csg w/25# per bbl. salt gel mud.
4. POOH. Perf. @ 1170' & sqz 85 sx cement w/pkr @ 1000'. Displace cmt below pkr. WOC & tag (top of salt 1122').
5. POOH. Spot 25 sx cmt plug f/775'-675' (top of Ruschler 725')
6. Perf. csg @ 450' & circ cmt to surface, bradenhead sqz.; leaving csg. full of cmt f/450'-surface @ 175 sxs cmt.
7. Nipple down BOP & cut off wellhead; cap well & install dry hole marker. Clean location & move off.

14. I hereby certify that the foregoing is true and correct

Signed [Signature]

Title Operations Engineer

Date 5/16/95

(This space for Federal or State office use)

Approved by Shannon J. Shaw

Title REGIONAL ENGINEER

Date 6/30/95

Conditions of approval, if any:

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

*See Instruction on Reverse Side

RECEIVED
JUL 11 1995
U.S. DEPARTMENT OF JUSTICE
FEDERAL BUREAU OF INVESTIGATION

RECEIVED

JUL 11 1995

U.S. DEPARTMENT OF JUSTICE
FEDERAL BUREAU OF INVESTIGATION
OFFICE