

(November 1983)
(Formerly 9-331)

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
P. O. BOX 1350

Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.
LC-061869

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐
Nov 17 11 24 AM '88

2. NAME OF OPERATOR
Texaco Inc.

3. ADDRESS OF OPERATOR
P.O. Box 728, Hobbs, New Mexico 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
Cotton Draw Unit

9. WELL NO.
35

10. FIELD AND POOL, OR WILDCAT
Paduca Delaware

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA
Sec 21, T25S, R32E

14. PERMIT NO.
36-025-08210

15. ELEVATIONS (Show whether DF, RT, GR, etc.)
3396.2 KB

12. COUNTY OR PARISH
Lea

13. STATE
NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
(Other) ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
ABANDON* ☐
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐
FRACTURE TREATMENT ☐
SHOOTING OR ACIDIZING ☐
(Other) ☐
REPAIRING WELL ☐
ALTERING CASING ☐
ABANDONMENT* ☒

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

- 10/24/88 BLM representative Bill McManus notified. MIRU PU. POH with 2-3/8" production tubing.
- 10/25/88 Set 4-1/2" CIBP at 4500' and cap with 35' of cement. Run free point survey, 4-1/2" casing stuck at 397'.
- 10/26/88 GIH with tubing and load hole with salt gel mud. POH. By WL, perforate 4-1/2" casing at 1130' with 4 JSPF. GIH with cement retainer and set at 1029'. Pump 300 sx Class "H" cement. Pull tubing to 420' and spot cement plug to surface. Install dry hole marker.
- 10/27/88 Clean location. RDPU. Change status from SI to P&A.

18. I hereby certify that the foregoing is true and correct

397-3571

SIGNED

[Signature]

TITLE Hobbs Area Superintendent

DATE 11-14-88

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

11-29-88

CONDITIONS OF APPROVAL, IF ANY:

Approved as to plugging
Liability under bond is retained until
surface restoration is completed.

*See Instructions on Reverse Side

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

R N

E