UNITED STATES DEPARTMENT OF THE INTERIOR

5.	LEASE
	LC-061869
-	JE INDIAN ALLOTTEE OF TRIPE NAME

GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	7. UNIT AGREEMENT NAME Cotton Draw Unit 8. FARM OR LEASE NAME	
1. oil gas otherWater Injection Well 2. NAME OF OPERATOR Texaco, Inc.	37 10. FIELD OR WILDCAT NAME	
3. ADDRESS OF OPERATOR P.O. Box 728, Hobbs, New Mexico 88240 4. LOCATION OF WELL (REPORT LOCATION CLEARLY See space 17 below) 660' FSL & 660' FWL AT SURFACE: AT TOP PROD. INTERVAL: AT TOTAL DEPTH:	Paduca Delaware 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 21, T-25-S, R-32-E 12. COUNTY OR PARISH 13. STATE Lea New Mexico 14. API NO.	
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)	
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES ABANDON* (other) TO: Set CIBP above Perfs. & Temporarily Abandon. 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is d measured and true vertical depths for all markers and zones pertinent 1. Rig up. Install BOP. Pull tubing 2. Set CIBP @ 4550' & spot 40' cement 3. Load casing w/inhibited water. 4. Temporarily abandon well.	irectionally drilled, give subsurface locations and to this work.)* g & packer.	
Subsurface Safety Valve: Manu. and Type	Set @ Ft.	
18. I hereby certify that the foregoing is true and correct		
SIGNED TITLE ASST. Dist.	Mgr DATE 2-22-82	
(This space for Federal or State off	ice use)	
APPROVED BY TITLE CONDITIONS OF APPROVAL, IF ANY:	APPROVED	

*See Instructions on Reverse Side

JAMES A. GILLHAM

RECEIVED

Lac 50 1982

HOBES UPFICE