Form 9-33 1 (May 1963)	DE	U' ED ST		SUBMIT IN TRIF (Other instruction verse side)	\TE• a re- 5.		oved. reau No. 42-R1424. on and Surial No.									
		GEOLOGICAL SURVEYOF O. C. B.				LC-062300										
	SUNDRY	100	0000		6,	IF INDIAN, ALLOT	TEE OR TRIBE NAME									
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen to plue balled Different reservoir. Use "APPLICATION FOR HAPPLIT" "Addition for the state of the second						NONE										
1.							7. UNIT AGREEMENT NAME									
OIL WELL	GAS GAS	OTHER				Cotton Drav	v Unit									
2. NAME O	F OPERATOR	MIEVA (O Tree			8.	PARM OR LEADE N	A M B									
8. ADDRESS	OF OPERATOR	TEXACO Inc.)			Cotton Dray	v Unit									
•••	P. O. Box 728 - Hobbs, New Mexico					9										
	LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.)					10. FIELD AND POOL, OR WILDCAT										
Well located 1980' from the North Line, and 660' from the West Line of Section 22, T-25-S, R-32-E, Lea County, New Mexico.						Paduca Delaware 11. SHC. T., B., M., OR BLK. AND SUBVEY OR ABBA Sec. 22, T-25-S, R-32-E										
									14. PERMIT	NO.	15. ELEVATIONS (Show whether DF, 1	RT, GR, etc.)		. COUNTY OR PARI	
									Regula	a r		з 414' (D. F	·•)		Lea	N. M.
16.	C	heck Appropriate Box	la Indicate No	iture of Notice Repor	t. or Othe	r Data										
		OF INTENTION TO :			SUBSEQUENT											
	Г															
	WATER SHUT-OFF	YULL OR ALTER CAS		WATER SHUT-OFF Fracture treatment	,	ALTERING										
	OR ACIDIZE	ABANDON*	-	SHOOTING OR ACIDIEI		ABANDONE	 									
REPAIR	WELL	CHANGE PLANS		(Other)												
(Other	r)	,				nultiple completion Report and Log										
propo	osed work. If well	LETED OPERATIONS (Clearly s is directionally drilled, give	tate all pertinent subsurface locatio	details, and give pertinent ons and measured and true	t dates, inclue vertical de	uding estimated d pths for all mark	ate of starting any ers and somes perti-									
nent	to this work.) *															
							·									
We	We propose to do the following work on subject well:															
ч	Tag bottom	with tubing and	aloon out	with cond num	if non	00007										
1.	Tag Doctom	with tubing. and	creau out	with same pump,	TT UEC	essary.										
2.	Pump lease	crude down tubing	g and casin	ng tubing annulu	S.		-									
	-															
3.		xisting perforations with 2000 gallons refined oil,				us 2000										
	pounds of s	and. Flush with	lease crud	le.												
4.	Swab well.	recover load oil,	test. and	l place well on	product	ion.										
	,	,	,,,	1	4											
						· · ·										
						•										
						· · · · · · · · · · · · · · · · · · ·										
19 T hanaha	- contidu that the f	pregoing is true and correct														
10. I Berevy		sregoug is true and correct	٨٥٩	sistant District		Anmi										
SIGNED	J. G. BI	evinst fr.		erintendent		DATE APIS	11 11, 1966									
(This sp	pace for Federal or	State office use)				SPON	EDT									
	VED BY		TITLE		FAP	KAY!	· · · · · · · · · · · · · · · · · · ·									
CONDI	TIONS OF APPROV	AL, IF ANY :				PR 1 2 196	0									
					۹ / ^۴	STO STAN	N I									
		*C.	e Instructione	on Reverse Side		A. R. BHOTH	EER									
				31/1 26/2/36 JUE		DISTRICT										