

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

N.M. Oil Con  
P 1980  
Hobbs NM 88241

FORM APPROVED  
Budget Bureau No. 1004-0135  
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

Texaco E & P, Inc.

3. Address and Telephone No.

P. O. Box 3109, Midland TX 79702 (915) 688-4492

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

510' FNL & 1830' FWL Unit Letter C  
S 22 - T25S - R32E

5. Lease Designation and Serial No.

LC-062300

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

Cotton Draw Unit

8. Well Name and No.

Cotton Draw Unit #16

9. API Well No.

30 025 08223

10. Field and Pool, or Exploratory Area

Paduca Delaware

11. County or Parish, State

Lea

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☒ Notice of Intent  
☐ Subsequent Report  
☐ Final Abandonment Notice

TYPE OF ACTION

- ☒ Abandonment  
☐ Recompletion  
☐ Plugging Back  
☐ Casing Repair  
☐ Altering Casing  
☐ Other

- ☐ Change of Plans  
☐ New Construction  
☐ Non-Routine Fracturing  
☐ Water Shut-Off  
☐ Conversion to Injection  
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

- 1) Notify BLM of intention to plug & abandon the well
- 2) MIRU, NUBOP, RIH W/workstring, Circ well bore W/25# per bbl salt gel mud
- 3) Set CICR @ 4550 & squeeze 15 sx cement
- 4) Spot 10 sx cement from 4500-4300
- 5) Spot 10 sx cement from 1257-1057
- 6) Circ cement to surface from 870-670 W/60 sx cement (perf @ 870)
- 7) Perf @ 380 & squeeze 60 sx cement 280-380 (shoe plug) WOC/Tag
- 8) Surface plug 10 sx cement
- 9) ND BOP, RDMO, cut off well head & install dry hole marker
- 10) Clean off location, move off well

RECEIVED  
1997 SEP 11 A 10:24  
BUREAU OF LAND MGMT.  
HOBBS, NEW MEXICO

14. I hereby certify that the foregoing is true and correct

Signed David W. Deas Title Reservoir Engineer

Date 9/10/97

(This space for Federal or State office use)

FOR: SGD J DAVID E. GLASS

Approved by PETROLEUM ENGINEER Title

Date SEP 11 1997

Conditions of approval, if any:

SEE ATTACHED FOR  
CONDITIONS OF APPROVAL

Title 18 U.S.C. Section 1001, makes it a crime to knowingly and willfully make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

\*See Instruction on Reverse Side