

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☒ gas ☐ other ☐
well well

2. NAME OF OPERATOR
TEXACO Inc.

3. ADDRESS OF OPERATOR
P. O. Box 728, Hobbs, New Mexico 88240

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 660' FNL & 600' FWL
AT TOP PROD. INTERVAL: (Unit Letter 'D')
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☐
(other) ☐

☐
☐
☐
☐
☐
☐
☐
☒

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. Rigged up. Install BOP.
2. Tagged CIBP @ 4475'.
3. Spot 118' (10 sx.) cement plug from 4460' - 4342'.
4. Cut 4 1/2" csg @ 1200' & pull 39 jts. (1200') 4 1/2" Csg.
5. Spot 184' (30 sx.) Cement plug from 1248'-1064'.
6. Spot 184' (30 sx.) Cement plug from 864'-680'.
7. Spot 99' (30 sx.) Cement plug from 384'-285'.
8. Spot 25' (6 sx.) Cement plug from 25' - Surface.
9. Install dry hole marker & clean location. Well P & A. 4-7-83.

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED [Signature] TITLE Asst. Dist. Mgr. DATE 4-8-83

(This space for Federal or State office use)

APPROVED BY [Signature] TITLE CAMS and RECORDS DATE 1-29-85

CONDITIONS OF APPROVAL, IF ANY:

5. LEASE
LC = 062300

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME
Cotton Draw Unit

8. FARM OR LEASE NAME
Cotton Draw Unit

9. WELL NO.
45

10. FIELD OR WILDCAT NAME
Paduca Delaware

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 28, T-25-S, R-32-E

12. COUNTY OR PARISH | 13. STATE
Lea | New Mexico

14. API NO.
30 025 08229

15. ELEVATIONS (SHOW DF, KDB, AND WD)
3380' (DF)

RECEIVED
APR 11 1983

(NOTE: Report results of multiple completion or zone change on Form 9-330)

OIL & GAS
MINERALS RIGHT SERVICE
ROSWell, NEW MEXICO

RECEIVED

FEB -1 1985

**O.C.D.
HOBBS OFFICE**