UNITED STATES

Э.	LEASE		
	LC-062300		
6.	IF INDIAN, ALLOTTEE OF	RTRIB	ENAME

DEPARTMENT OF THE INTERIOR	LU-002300
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.) 1. oil gas well other Water Injection Well 2. NAME OF OPERATOR Texaco, Inc. 3. ADDRESS OF OPERATOR P.O. Box 728, Hobbs, New Mexico 88240 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) 330' FNL & 330' FEL AT SURFACE: (Unit Letter 'A') AT TOP PROD. INTERVAL: AT TOTAL DEPTH: 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF GRACIURE TREAT GRACIURE TRACIURE TREAT GRACIURE TRACIURE TRACIURE TR	7. UNIT AGREEMENT NAME Cotton Draw Unit 8. FARM OR LEASE NAME Cotton Draw Unit 1 9. WELL NO. 55 10. FIELD OR WILDCAT NAME Paduca Delaware 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 29, T-25-S, R-32-E 12. COUNTY OR PARISH Lea New Mexico 14. API NO. 15. ELEVATIONS (SHOW DF, KDB, AND WD) 3376' (DF) (NOTE: Report results of multiple completion or zone 1982 change on Form 9-330.) e all pertinent details, and give pertinent dates, irrectionally drilled, give subsurface locations and not to this work.)*
1. Rig up. Install BOP. Pull tubing	g & packer.
2. Set CIBP @ 4650' & spot 40' Cement	t on plug.
3. Load casing w/inhibited water.	
4. Temporarily abandon Well.	
Subsurface Safety Valve: Manu. and Type	Set @ Ft.

TITLE Asst. Dist. Mgr DATE

(This space for Federal or State office use)

18. I hereby certify that the foregoing is true and correct

APPROVED

MAR 29 1982

JAMES A. GILLHAM DISTRICT SUPERVISOR

*See Instructions on Reverse Side