

Form 3160-5  
(June 1990)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

N.M. OIL CONS. COMMISSION  
P.O. BOX 1980  
HOBBS, NEW MEXICO 88240

FORM APPROVED  
Budget Bureau No. 1004-0135  
Expires: March 31, 1993

5. Lease Designation and Serial No.  
LC-062300

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

Unit A

8. Well Name and No.

Cotton Draw Unit #56

9. API Well No.

30-02508236

10. Field and Pool, or Exploratory Area  
Paduca Delaware

11. County or Parish, State

Lea, NM

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☐ Oil Well ☐ Gas Well ☒ Other injection

2. Name of Operator

Texaco E&P, Inc.

3. Address and Telephone No.

P. O. Box 3109 - Midland, TX 79702

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Unit A 660' FNL, 990' FEL Sec. 28 T-25S R-32E

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☒ Notice of Intent  
☐ Subsequent Report  
☐ Final Abandonment Notice

TYPE OF ACTION

- ☒ Abandonment  
☐ Recompletion  
☐ Plugging Back  
☐ Casing Repair  
☐ Altering Casing  
☐ Other

- ☐ Change of Plans  
☐ New Construction  
☐ Non-Routine Fracturing  
☐ Water Shut-Off  
☐ Conversion to Injection  
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

1. Notify BLM prior to plugging & abandonment of well.
2. TIH w/ tub. to 4500'. Circ. csg. w/25# per bbl. salt gel mud.
3. POOH to 4406'. Spot 25 sx cmt f/4406' - 4206' (Btm of salt; 4356').
4. Perf. & sqz 85 sx cmt @ 1182' w/pkr @ 1000'. WOC & tag. (Top of salt 1132').
5. POOH to 788'. Spot 25 sx cmt plug f/788'-588' (Russler @ 738').
6. Perf. @ 405' & circ. cmt to surface behind 4½" casing. Leave inside of 4½" casing full of cement @ 405' to surface.
7. Nipple down BOP & cut off wellhead; cap well & install dry hole marker. Clean up location & move off.

14. I hereby certify that the foregoing is true and correct

Signed

Title Operations Engineer

Date

(This space for Federal or State office use)

Approved by Shannon J. Shaw

Title

Date

Conditions of approval, if any:

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

\*See Instruction on Reverse Side