

Form 9-881a  
(Feb. 1961)

			0

1961

(SUBMIT IN TRIPLICATE)

HOBBBS OFFICE CO.

Budget Bureau No. 43-2388.4  
Approval expires 12-31-60.

Land Office Santa Fe

Lease No. LC 068846

Unit "D"

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

*Inspected 3-2-61  
O.K. for addmt J.L.G.*

SUNDRY NOTICES AND REPORTS ON WELLS

OCT 1

U.S. GEOLOGICAL SURVEY  
HOBBBS, NEW MEXICO

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	X
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Hill & Meeker - Bass Federal "5" August 3, 1960

Well No. 1 is located 660 ft. from N line and 660 ft. from E line of sec. 5

N/2 of NE 4  
(1/4 Sec. and Sec. No.)

25S  
(Twp.)

33E  
(Range)

N.M.P.M.  
(Meridian)

Wildcat  
(Field)

Lea  
(County or Subdivision)

New Mexico  
(State or Territory)

The elevation of the derrick floor above sea level is 3478 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Well drilled to 5081 ft. - Cored 5081 to 5193' - No shows - Ran logs  
Prep to plug

Cement Plugs as follows -

10 sks at surface

10 sks at 420' - bottom surface csg at 410'

25 sks at 1110' - Top Rustler at 1105'

25 sks at 1440' - Bottom Rustler at 1425'

25 sks at 5081' - Bottom Lamar or Black Shale 5080'

Hole full mud laden material

4" marker 4' above G.L. - Clean up - Oral permission by Mr. Stanley  
July 7, 1960

MAR 1961

GORDON

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company HILL & MEKKER

Address 519 Midland Savings & Loan Bldg.

Midland, Texas

By [Signature]

Title Production Clerk

30-025-08380