


NOV 26 1962

Budget Bureau No. 42-R358.4.
Form Approved.E. W. STANDLEY
DISTRICT ENGINEER

(SUBMIT IN TRIPLICATE)

HOBBS

UNITED STATES

DEPARTMENT OF THE INTERIOR

GEOLOGICAL SURVEY

Land Office New Mexico

Lease No. 30-025-08385

Unit

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Well No. 30-025-08385 is located _____ ft. from _____ line and _____ ft. from _____ line of sec. _____
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
_____ (Field) _____ (County or Subdivision) _____ (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

The well was plugged and abandoned as follows:

1. 10 sacks of cement at 1225'.

2. 10 sacks of cement at 1225'.

3. 10 sacks of 3074' (bottom of hole)

4. 10 sacks of 4725' (bottom of salt)

5. 10 sacks of 1225' (top of salt)

6. 10 sacks of 300' (bottom of surface casing)

Identification marker and 10 sacks cement at surface.
Location to be cleared as soon as bits are dry.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Turtle Tanker

Address 114 Security National Bank Bldg.

New Mexico

By

Title

30-025-08385