

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT


SUBMIT IN TRIPLICATE
(Other instructions on
reverse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. UNIT AGREEMENT NAME Wells H
2. NAME OF OPERATOR CONOCO INC.	8. FARM OR LEASE NAME Wells A
3. ADDRESS OF OPERATOR P. O. Box 460, Hobbs, N.M. 88240	9. WELL NO. 1
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface Unit M 660' FSH & 330' FWH	10. FIELD AND POOL, OR WILDCAT Jalmat Yates Gas
14. PERMIT NO. 30-625-09719	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA SEC. 1 - 25S-36E
15. ELEVATIONS (Show whether DF, RT, GR, etc.)	12. COUNTY OR PARISH Lea
	13. STATE NM



16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	☐	WATER SHUT-OFF	☐
FRACTURE TREAT	☐	FRACTURE TREATMENT	☐
SHOOT OR ACIDIZE	☐	SHOOTING OR ACIDIZING	☐
REPAIR WELL	☐	(Other)	☐
(Other)	☐		
PULL OR ALTER CASING	☐	REPAIRING WELL	☐
MULTIPLE COMPLETION	☐	ALTERING CASING	☒
ABANDON*	☐	ABANDONMENT*	☐
CHANGE PLANS	☐		

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

1. MURK.
2. G-1H w/hydro-much CIBP, to 2847'. Open end to CIBP at 2847'.
3. CIBP at 2847'. Spot 8 sxs from 2847'-2772'. Spot 13 sxs cmt from 1200'-1074'. Well tag plug 1074'. Well set 50' surface plug. Install P&A marker.
4. Tag cmt plug at 1100'. Load surface csq annulus w/6 bbls mud. Set surface plug top 60' w/ class "C" cmt 4% CaCl₂. Top cut csq w/cmt. Welded plate on csq, welded up P&A marker. Clean location.

18. I hereby certify that the foregoing is true and correct

SIGNED David L. Marl TITLE Administrative Supervisor DATE 3-6-87

FOR APPROVAL OF FEDERAL OR STATE OFFICE USE:

SIGNED Orig. Sgd. David L. Marl TITLE AREA MANAGER CARLSBAD RESOURCE AREA DATE 4-24-87

COPIES OF APPROVAL, IF ANY:

*See instructions on Reverse Side



RECEIVED
APR 27 1987
OCD
HOBBS OFFICE