

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIAL
(Check instructions
verse side)

P. O. Box 1060
HOBBS, NEW MEXICO

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

6S-032582A

6. INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL ☒ WELL GAS ☐ WELL OTHER ☐

2. NAME OF OPERATOR

Conoco Inc.

3. ADDRESS OF OPERATOR

P. O. Box 460 - Hobbs NM 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)

At surface 2310' FNH & 990' FEL Unit Letter H

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Wells A

9. WELL NO.

3

10. FIELD AND POOL, OR WILDCAT

Jalmat Yates Seven Rvrs

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

11-25S-36E

14. PERMIT NO.

30-025-09732

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

12. COUNTY OR PARISH

Lea

13. STATE

NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☐
☐
☐
☐
☐

PULL OR ALTER CASING

☐
☐
☐
☐
☐

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

☐
☐
☐
☐
☐

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

☐
☐
☒
☐
☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Work started 3/6/87 and completed 3/11/87. MIRR. Tag fell at 3437'. Rmpd 3 bbls fresh water down Hg to establish circ. Hg press up to 1000 psi. Plug off. Rmpd 35 bbls fresh water. Spot cmt plug in OH section. Rmpd 31 bbls fresh water down Hg to lead hole & est circ. Mix & pump 100 sxs class "C" cmt w/4% CaCl₂ & 1/4#/sx celloflake. Displace w/13 bbls fresh water. Tag top of cmt plug at 2922'. Set CIBP at 2902. Press test csq & CIBP to 500 psi. G1H w/2 7/8" Hg open ended 2898'. Mix up & circ wellbore w/170 bbls brine gel mud. Spot 25 sxs at 2888'. Plug to top of CIBP w/25 sxs class "C" cmt w/4% CaCl₂ & 1/2#/sx celloflake at 2 BPM. Displace w/16 bbls brine gel at 4 BPM. Perf at 1150' w/2; spf. Load hole w/5 bbls brine gel. Press up to 600 psi. Perf at 1050' w/4; spf. Pump

18. I hereby certify that the foregoing is true and correct

WITNESSED BY David L. Mari TITLE Administrative Supervisor DATE April 14, 1987

FOR SUBMITTER'S USE (Federal or State office use)

APPROVED BY David L. Mari TITLE AREA MANAGER DATE 4-24-87

COMMENTS OF APPROVAL, IF ANY:

Approved for drilling of the well bore.
Licenses for the well bore and until
submitted to the BLM for completion.

*See instructions on Reverse Side

Section 102 of the National Historic Preservation Act, 16 U.S.C. 1101, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

BLM-Carlsbad(6) ARCC(2) AMOCO(2) CHEVRON(1) FILE