

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRII
(Other instructions
verse side)

Form approved.
Budget Bureau No. 1004-0115
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.
LC 032582

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR TENISON OIL COMPANY	8. FARM OR LEASE NAME E. J. Wells
3. ADDRESS OF OPERATOR 8140 Walnut Hill Lane, Suite 601, Dallas, TX. 75231	9. WELL NO. 1 (H)
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 2310' from N line 990' from E line Sec. 12, T25S R36E Unit H	11. SEC., T., R., M., OR BLK. AND SURVEY OR ARMA S12 T25S R36E
14. PERMIT NO.	12. COUNTY OR PARISH Lea
15. ELEVATIONS (Show whether DF, RT, CR, etc.) 3176 DF	13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input checked="" type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANK <input type="checkbox"/>	(Other) <input type="checkbox"/>	

(Other) ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Estimated start date - July 2, 1991

1. Wash to bottom of 5½" casing at +/- 2862'.
2. Set a CIBP at 2850'.
3. Perforate the following intervals w/2 shots per foot; 2764'-67', 2476'-80', 2894'-2808', 2812'-2814', 2816'-2820', 2825'-2829', 2834'-2838'.
4. Run tubing, pump & rods.
5. Pump test well.

RECEIVED
JUN 27 11 20 AM '91
CARLE AREA MANAGERS

18. I hereby certify that the foregoing is true and correct

SIGNED <u>[Signature]</u>	TITLE <u>Operations Manager</u>	DATE <u>6/25/91</u>
(This space for Federal or State office use)		
APPROVED BY <u>[Signature]</u>	TITLE <u></u>	DATE <u>7-5-91</u>
CONDITIONS OF APPROVAL, IF ANY:		

*See Instructions on Reverse Side

RECEIVED

JUL 09 1991

000

HOBBS OFFICE