

DUPLICATE

NEW MEXICO OIL CONSERVATION COMMISSION
Santa Fe, New Mexico

MISCELLANEOUS REPORTS ON WELL

RECEIVED
APR 8 - 1940
OIL & GAS DIVISION

Submit this report in triplicate to the Oil Conservation Commission or its proper agent within ten days after the work specified is completed. It should be signed and sworn to before a notary public for reports on beginning drilling operations, results of shooting well, results of test of casing shut-offs, result of plugging of well, and other important operations, even though the work was witnessed by an agent of the commission. Reports on minor operations need not be signed and sworn to before a notary public. See additional instructions in the Rules and Regulations of the Commission.

Indicate nature of report by checking below:

REPORT ON BEGINNING DRILLING OPERATIONS		REPORT ON REPAIRING WELL	
REPORT ON RESULT OF SHOOTING OR CHEMICAL TREATMENT OF WELL		REPORT ON PULLING OR OTHERWISE ALTERING CASING	
REPORT ON RESULT OF TEST OF CASING SHUT-OFF		REPORT ON DEEPENING WELL	
REPORT ON RESULT OF PLUGGING OF WELL	X		

Hobbs, New Mexico, April 4, 1940.

Place

Date

OIL CONSERVATION COMMISSION,
Santa Fe, New Mexico.

Gentlemen:

Following is a report on the work done and the results obtained under the heading noted above at the

Repollo Oil Company S. M. Gloyd Well No. 1 in the
COMPANY OR OPERATOR LEASE
SE/4 of Sec. 12, T. 25S, R. 36E, N. M. P. M.,
Jal Field, Lea County

The dates of this work were as follows: 2/28/40

Notice of intention to do the work was (was not) submitted on Form C-102 on 2/19/40 19
and approval of the proposed plan was (~~not~~) obtained. (Cross out incorrect words)

DETAILED ACCOUNT OF WORK DONE AND RESULTS OBTAINED

- 2/24/40- Pulled Tubing & re-run to cement bottom
2/25/40- Cemented bottom (3133') with 25 sacks cement Filling casing to top with heavy mud
2/26/40- Shot off 7"OD Casing @ 2450' and pulled keeping hole full heavy mud.
2/27/40- Completed pulling 7"OD Casing
2/28/40- Set 15 sack cement plug @ 1000' ~~through~~ through tubing, keeping hole full heavy mud. Shot off 10 1/2"OD Casing @ 60' and pulled same. Filled hole to bottom of cellar with heavy mud. Set 1 piece of 4" pipe in 5 sacks cement in bottom of cellar of sufficient length to extend 4' above the surface level as a "Regulation Marker"
Well Completely plugged

Witnessed by _____
Name Company Title

Subscribed and sworn to before me this 4thday of April, 19

[Signature]
Notary Public

My Commission expires 2-4-42

I hereby swear or affirm that the information given above is true and correct

Name [Signature]Position Dist. Supt.Representing Repollo Oil Company
Company or OperatorAddress Hobbs, N.M.

Remarks:

[Signature]
OIL & GAS INSPECTOR

Title