

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

5. Lease Designation and Serial No.

LC 032581A

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

SUBMIT IN TRIPLICATE

1. Type of Well

☐ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

Conoco Inc

3. Address and Telephone No.

10 Desta Drive STE 100W, Midland, TX 79705 (915)686-5424

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

2310' FSL & 2310' FEL, SEC. 13, T-25S, R-36E, UNIT LTR "J"

8. Well Name and No.

SHOLES "A" #6

9. API Well No.

30-025-09760

10. Field and Pool, or Exploratory Area

JALMAT YATES 7 RVRS TRANS

11. County or Parish, State

LEA, NM

CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☐ Notice of Intent

☒ Subsequent Report

☒ Final Abandonment Notice

TYPE OF ACTION

☒ Abandonment

☐ Recompletion

☐ Plugging Back

☐ Casing Repair

☐ Altering Casing

☐ Other

☐ Change of Plans

☐ New Construction

☐ Non-Routine Fracturing

☐ Water Shut-Off

☐ Conversion to Injection

☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or P recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

5-17-92 MIRU. RIH W/ TBG & CMT RETAINER, PUMP 50 SX CMT ON TOP OF RETAINER, CIRC MUD.
PUH PUMP 50 SX CMT FRC 2766-2466, POOH.
PERF AT 1600' CIRC MUL, PUMP 45 SX CMT FROM 1600-1450', POOH.
RIH TAG CMT @ 1560'. SPOT 10 SX CMT AT 1560 TO 1450'.
PUH SPOT 25 SX CMT 1320' TO 1170, POOH. RIH TAG CMT AT 1130'.
PERF AT 200'. PUMP 110 BLS MUD-NO RETURNS. PUMP 50 SX CMT-WAIT 4 HRS. PUMP 120 SX CMT
DISPLACE TO 200'. RIH TAG CMT @ 200'.
PUMP 25 SX CMT, CIRC CMT TO SURFACE. CMT TO SURFACE INSIDE 9 5/8".
PUMP 25 SX CMT DOWN 13", CUT OFF WELLHEAD.
RDMO
INSTALL P&A MARKER.
WELL P&A ON 5-22-91

Approved
Date
Signature

14. I hereby certify that the foregoing is true and correct

Signed Eric R. Seasholtz

Title SR REGULATORY SPEC.

Date 7-1-92

(This space for Federal or State office use)

Approved by

Conditions of approval, if any:

Title

Date

7-14-92