FORM C-103





Titie

MISCELLANEOUS REPORTS ON WELL

à.

Submit this report in triplicate to the Oil Conservation Commission or its proper agent within the safet of the work specified is completed. It should be signed and sworn to before a notary public for reports on beginning drilling operations, results of shooting well, results of test of casing shut-offs, result of plugging of well, and other important operations, even though the work was witnessed by an agent of the commission. Reports on minor operations need not be signed and sworn to before a notary public. See additional instructions in the Rules and Regulations of the Commission.

| Indicate n | nature of | report | by c | hecking | below: |
|------------|-----------|--------|------|---------|--------|
|------------|-----------|--------|------|---------|--------|

| | OTING OR CHEMICAL | | ON PULLING O | R OTHERWISE | |
|--|--|--|---|--|---|
| TREATMENT OF WELL REPORT ON RESULT OF TES | T OF CASING | | RING CASING | | |
| SHUT-OFF | | | DN DEEPENING | | |
| REPORT ON RESULT OF PL | | X | | | |
| | Hobbs, New | Mexico, | Februar | y 6, 1940 | |
| OIL CONSERVATION COM Santa Fe, New Mexico. | IMISSION, | Place | | Date | |
| Gentlemen: | | | | | |
| Following is a report on the Repollo Oil Comp | | .Stephens" | A H | r | |
| COMPAN | Y OR OPERATOR | LEASE | Y | Vell No. | in the |
| <u>NE/4</u> | of Sec. 15 | <u>, T. 258</u> | , 10 | 36 E | N. M. P. M., |
| Jal | Field, | Le | | | County |
| The dates of this work we | ere as follows: | 12/26/39 8 | c 2/5/40 | | |
| g hole full mud | to bottom of cel | lar. Tempo | rary shu | t down. | |
| th, filled hole og hole full mud th, set 15 sack "OD casing @ 20 "OD Casing keepi of sufficient tom of cellar as | to bottom of cel cement plug @ 18 feet and pulled, ng hole full hea length to extend | lar. Tempo ilo'top of set 10 se vy mud to 4' above | shot off ck cemen bottom o the surf | t down. 7"OD Casin t plug in t f cellar. S ace levet f | ng, shot o top of sho Set a pice |
| g hole full mud th, set 15 sack "OD casing @ 20 "OD Casing keepi of sufficient tom of celler as d. 2 tons mud ment plugs throu Witnessed by <u>Mr.</u> | to bottom of cel cement plug © 18 feet and pulled, ng hole full hea length to extend "Regulation Mar | lar. Tempo Blo'top of set 10 sa wy mud to 4' above ker" and f | orary shu shot off ack cemen bottom o the surf filled ce | t down. 7"OD Casin t plug in t f cellar. S ace levet f | ng, shot o top of sho Set a piec in 5 sacks complete |
| g hole full mud th, set 15 sack "OD casing @ 20 "OD Casing keepi • of sufficient tom of celler as d. 2 tons mud ment plugs throu Witnessed by <u>Mr</u> . | to bottom of cel cement plug © 18 feet and pulled, ng hole full hea length to extend "Regulation Mar gh tubing. Joe Persky Name | lar. Tempo alo'top of set 10 se vy mud to 4' above ker" and f Lea CC Company I hereby sw is true and | orary shu shot off ack cemen bottom o the surf filled ce | t down. 7"OD Casin t plug in t f cellar. S ace leveit i llar . Well | ng, shot of top of sho Set a piec in 5 sacks complete |
| g hole full mud th, set 15 sack "OD casing @ 20 "OD Casing keepi • of sufficient tom of celler as d. 2 tons mud ment plugs throu Witnessed by <u>Mr</u> . | to bottom of cel cement plug © 18 feet and pulled, ng hole full hea length to extend "Regulation Mar gh tubing. Joe Persky Name | lar. Tempo act 10 set vy mud to 4' above ker" and f Lea CC Company I hereby sw | orary shu shot off ack cemen bottom o the surf filled ce | t down. 7"OD Casin t plug in t f cellar. S ace level i llar . Well ing Pullers | ng, shot of top of sho Set a piec in 5 sacks complete |
| g hole full mud th, set 15 sack "OD casing @ 20 "OD Casing keepi • of sufficient tom of celler as d. 2 tons mud ment plugs throu Witnessed by <u>Mr</u> . | to bottom of cel cement plug © 18 feet and pulled, ng hole full hea length to extend "Regulation Mar gh tubing. Joe Persky Name | lar. Tempo alo'top of set 10 se wy mud to 4' above ker" and f Lea CC Company I hereby sw is true and Name | orary shu shot off ack cemen bottom o the surf filled ce | t down. 7"OD Casin t plug in t f cellar. S ace level i llar . Well ing Pullers that the informat | ng, shot of top of sho Set a piec in 5 sacks complete |
| g hole full mud th, set 15 sack "OD casing @ 20 "OD Casing keepi • of sufficient tom of celler as d. 2 tons mud ment plugs throu Witnessed by <u>Mr</u> . | to bottom of cel cement plug © 18 feet and pulled, ng hole full hea length to extend "Regulation Mar gh tubing. Joe Persky Name | lar. Tempo ilO'top of set 10 set vy mud to 4' above ker" and f Lea CC Company I hereby sw is true and Name Position | prary shu shot off ack cemen bottom o the surf filled ce | t down. 7"OD Casin t plug in t f cellar. S ace level i llar . Well ing Pullers that the informat | ng, shot of top of sho Set a pleo in 5 sacks complete |
| g hole full mud th, set 15 sack "OD casing @ 20 "OD Casing keepi • of sufficient tom of celler as d. 2 tons mud ment plugs throu Witnessed by <u>Mr</u> . | to bottom of cel cement plug 2 18 feet and pulled, ng hole full hea length to extend "Regulation Mar gh tubing. Joe Fersky Name re me this 6th b | lar. Tempo ilO'top of set 10 set vy mud to 4' above ker" and f Lea CC Company I hereby sw is true and Name Position | prary shu shot off ack cemen bottom o the surf filled ce ounty Cass wear or affirm correct. Dist. Su | t down. 7"OD Casin t plug in t f cellar. S ace level i llar . Well ing Pullers that the informat U upt. Oil Co Company or | ng, shot of top of sho Set a pleo in 5 sacks complete |