(Pob), 1000			U.S Office Leas U.	
DEPARTMENT OF THE INTERIOR		Serial Number 032651		
GEOLOGICA SUNDRY NOTICES 2	ANE	REPORTS O	Loss XXXX Lease N WELLS	
NOTICE OF INTENTION TO DRILL		SUBSEQUENT RECORD OF SHOO	TING	
NOTICE OF INTENTION TO CHANGE PLANS				
NOTICE OF DATE FOR TEST OF WATER SHUT-OFF	- i iš			
REPORT ON RESULT OF TEST OF WATER SHUT-OFF				
NOTICE OF INTENTION TO REPAIR WELL			OONMENT	
NOTICE OF INTENTION TO SHOOT			Y	
Following is a {notice of intention to do report of work done State of Now Nexico				
(State or Territory)	(Соыл	ty or Subdivision)	(Field)	
Well No. <u>1-1</u> <u>MEETANE Sec.</u> (½ Sec. and Sec. No.)	<u>24</u> ,	<u>25 2, 36</u> (Twp.) (Re	<u>B. N.N.P.T.</u> nge) (Meridian)	
The well is located <u>520</u> ft. ${S S S f}$ of <u>N</u> lin	ne and	$\frac{1980 \text{ ft. } {E}}{W} \text{ of } \underline{W}$	_ line of sec24	
The elevation of the derrick floor above sea le	vel is	<u>32.24</u> ft.		
~~~~~~		PLAN OF WORK		
State names of and expected depths to objective sands; show sizes, all other	weights, importa	and lengths of proposed casings; i nt proposed work.)	ndicate mudding jobs, cementing poin	
This well stopped flowing on sequent flows during the firs	or	about Jan. 20t	h. It made 3 or	

Mar. 8th the acid was unloaded; the well flowed for 12 hours, and again quit flowing. It flowed for 2 hours on Mar. 9th and 2 hours on Mar. 10, and has not been flowing since that time. The acid gave it a slight increase in gas and a slight increase in water, making approximately 50% water at the time. Derrick has been errected and we intend to set Howe pump at the 2,000 foot depth.

We expect to have this well back on production by the 22d or 23d of March, 1935.

Approved <u>Linreh 20, 1955</u>	$\begin{array}{c} \text{Company} \\ 50 \\ 11 \\ 11 \end{array}$	UTUERN PE	TROIDUM EMPLORA	
Supervisor, Off & Gas Operations	Ву			
Title Thomas G. Taylor, Encineer Geological SURVEY	Title		Agent	
Address Rosvell, New Mozico.	Address	Roswell,	Nev Llexico	
NGTEReports on this form to be submitted in triplicate to the Supervisor for approval.		801	SERVICE FRONTERS OFFICE 6-7953	