

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
HOBBS, NEW MEXICO 88240

SUBMIT IN TRIPLICATE
Other instructions on re-
verse side

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985
LEASE DESIGNATION AND SERIAL NO.

LC-032581(B)

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR
CONOCO INC.

3. ADDRESS OF OPERATOR
P. O. Box 460, Hobbs, N.M. 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

14. PERMIT NO.
API # 30-025-09810

15. ELEVATIONS (Show whether DF, RT, GR, etc.)
660' FNL & 660' FEH

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME
NMFU

8. FARM OR LEASE NAME
Sholes B-25

9. WELL NO.
4

10. FIELD AND POOL, OR WILDCAT
Jalmat Yates 7 Rvrs

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA
Sec 25-25S-36E

12. COUNTY OR PARISH 13. STATE
Lea NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(Note: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

MIRU on 5/20/85. Ran GR-CLH & CBL log from 2993'-1993'. Set CIBP @ 2968'. Leak betw. 2923'-2962'. Spot 5 bbls 15% HCL. Perf w/1 jspt @ 2939', 40', 41', 42', 43', 44', 50', 51', 52', 53', 54', 55', 56' & 57' for total of 14 holes. Set RBP @ 2968' & pkr @ 2831'. Pmpd total of 28.6 bbls 15% HCL-NE-FE acid & 600# rocksalt in 3 stages. Flushed to perfs. Reset RBP @ 2923'. Spot 5 bbls 15% HCL-NE-FE acid from 2908'-2899'. Perf w/1 jspt @ 2899', 2900', 01', 02', 03', 06', 07' & 08' for total 8 holes. Pmpd 16 bbls 15% HCL-NE-FE. Swab. Hang well on. Pmpd 7 BO, 506 BW & 27 mcf on 5/29/85.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Administrative Supervisor

DATE

7/10/85

(This space for Federal or State office use)

APPROVED BY

ACCEPTED FOR RECORD

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

JUL 15 1985

*See Instructions on Reverse Side

RECEIVED

JUL 17 1985

12-12-85
12-12-85