

NEW MEXICO OIL CONSERVATION COMMISSION

N. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT TO DRILL" FORM C-101 FOR SUCH PROPOSALS.

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator <b>Lonnie J. Suck</b>	8. Farm or Lease Name <b>Monco</b>
3. Address of Operator <b>901 North Jefferson Hobbs, New Mexico</b>	9. Well No. <b>#1</b>
4. Location of Well UNIT LETTER <b>L</b> <b>990</b> FEET FROM THE <b>West</b> LINE AND <b>2310</b> FEET FROM THE <b>South</b> LINE, SECTION <b>25</b> TOWNSHIP <b>25S</b> RANGE <b>36E</b> N.M.P.M.	10. Field and Pool, or Wildcat <b>Jalmat</b>
15. Elevation (Show whether DF, RT, GR, etc.)	12. County <b>Lea</b>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Set bridge plug at 3140'. perforate 3094-3110; 3052-53; 3042-43-44-45; 3033-34-35 w/ 1 jspl. (26 shots). Treat w/ 2400 gals 15% NE acid. Swabbed 20 bbls of load. Shut in. 425# tubing pressure, Killed w/ 50 bbls. water, Remove packer & BOP. Returned to pumping to recover 140 bbls. load.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Lonnie J. Suck</u>	TITLE <u>owner-operator</u>	DATE <u>7-5-79</u>
APPROVED BY <u>Jerry Sexton</u>	TITLE <u>Dist 1, Supv.</u>	DATE <u>JUL 11 1979</u>
CONDITIONS OF APPROVAL, IF ANY		