

to appropriate  
District Office

## DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

## DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

## DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

## OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.	30 025 11140
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil / Gas Lease No.	NM 12612
7. Lease Name or Unit Agreement Name	COOPER JAL UNIT
8. Well No.	117
9. Pool Name or Wildcat	JALMAT TANSILL YATES SEVEN RIVERS
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMI  
(FORM C-101) FOR SUCH PROPOSALS.

1. Type of Well: OIL WELL ☐ GAS WELL ☒ OTHER ☐

2. Name of Operator  
TEXACO EXPLORATION & PRODUCTION INC.

3. Address of Operator  
205 E. Bender, HOBBS, NM 88240

4. Well Location  
Unit Letter N : 660 Feet From The SOUTH Line and 1980 Feet From The WEST Line  
Section 18 Township 24S Range 37E NMPM LEA COUNTY

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

## SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPERATION <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	C/O & ACIDIZE <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

9-08-00: MIRU. WELLCHECK TBG OUT OF HLE. TAG FILL @ 3140'

9-11-00: TIH W/BIT, DC'S ON TBG. RU FOAM UNIT & BREAK CIRC. C/O SAND IN CSG 3140-3268-PBTD. PULL TO 3006'.

9-12-00: LOWER TOOLS & TAG FILL @ 3256'. C/O SAND TO 3268-12/ TIH W/SONIC HAMMER TOOL ON TBG. STOP TOOL @ 2990'.

9-13-00: ACID WASH JALMAT CSG PERFS 3058-3078 W/1000 GAL;S 15% NEE HCL & 92 BABLS 2% KCL WTR. SCALE SQUEEZE SAME PERFS W/165 GALS TH-756. PULL TOOL TO 3050'.

9-14-00: LOWER TOOLS & TAG @ 3268'. NO FILL. TIH W/PURGE VALVE, SN, TBG, TAC. TBG @ 3117'. SN @ 3090'. TAC @ 2994'. ND BOP. NUWH. TIH W/FILTER, EXT, PUMP, & RDS. HANG ON. LOAD & TEWST TO 500#.

9-15-00: RIG DOWN. TEST

10-09-00: PULL RDS & PMP. FILTER WAS PLUGGED W/IRON SULFIDE. RAN BACK IN W/2X1 1/4" STROKE THRU PUMP. CLAMP OFF RDS. RIG DOWN.

10-10-00: SET OFF UNIT & MOVE IN & SET NEW UNIT.

10-26-00: ON 24 HR OPT. PUMPED 0 BO, 46 BW, & 96 MCF.

## FINAL REPORT

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. Denise Leake TITLE Engineering Assistant

DATE 11/1/00

TYPE OR PRINT NAME J. Denise Leake

Telephone No. 397-0405

(This space for State Use)

APPROVED

CONDITIONS OF APPROVAL IF ANY:  TITLE

DATE

