

Submit 3 Copies To Appropriate District Office

District I

1625 N. French Dr., Hobbs, NM 88240

District II

811 South First, Artesia, NM 88210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION

2040 South Pacheco

Santa Fe, NM 87505

Form C-103

Revised March 25, 1999

WELL API NO. 30-025-11166
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. NM-12612
7. Lease Name or Unit Agreement Name: Cooper Jal Unit
8. Well No. 147
9. Pool name or Wildcat Tansill, Y 7 Rvrs / Jalmat Langlie Mattix

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other Injection Well	
2. Name of Operator Texaco Exploration & Production, Inc	8. Well No. 147
3. Address of Operator P. O. Box 3109, Midland, Tx 79702	9. Pool name or Wildcat Tansill, Y 7 Rvrs / Jalmat Langlie Mattix
4. Well Location Unit Letter <u>E</u> : <u>2310</u> feet from the <u>North</u> line and <u>330</u> feet from the <u>West</u> line Section <u>19</u> Township <u>24S</u> Range <u>37E</u> NMPM Lea County	
10. Elevation (Show whether DR, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. MI & RU Plugging Equipment. 3/28/01
2. Set 4 1/2 CIBP @ 2950'. 3/29/01
3. Spot 75 sx Class C Cmt @ 2950'. Tag Toc @2545'. 3/29/01
4. Perf. @ 1200', Squeezed 50 sx Class C Cmt Tag Toc @995'. 3/30/01
5. Perf. @ 300', Circ. 120 sx Class C Cmt Down 7" Csg, Out @ Perfs & up 7 x 9 5/8 Ann to Surface. 3/30/01
6. Installed Dry Hole Marker. 3/31/01

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Jimmy Bagley TITLE MANAGER DATE 3/31/01

Type or print name Jimmy BAGLEY Telephone No. _____

(This space for State use)

APPROVED BY [Signature] TITLE Adm. Sec. DATE 6-14-01

Conditions of approval, if any:

res [Signature]

