	- 	
NO. OF COPIES RECEIVED		Form C-103
DISTRIBUTION		Supersedes Old
SANTA FE	NEW MEXICO OIL CONSERVATION COMMISSION	C-102 and C-103 Effective 1-1-65
FILE		
U.S.G.S.		5a. Indicate Type of Lease
LAND OFFICE		State Fee X
OPERATOR		5. State Oil & Gas Lease No.
SUND	RY NOTICES AND REPORTS ON WELLS ROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. TION FOR PERMIT " (FORM C-101) FOR SUCH PROPOSALS.)	
	TION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	
1. OIL GAS WELL	· ·	7. Unit Agreement Name
2. Name of Operator	OTHER-	8. Farm or Lease Name
McCulloch	Arco-Jamison	
3, Address of Operator		
	9. Well No.	
	Towers East, Midland, Texas, 79701	
4. Location of Well	554 FEET FROM THE NORTH LINE AND 766	10. Field and Pool, or Wildcat Fowler (Upper Yeso)
	22 <u>TOWNSHIP</u> <u>24-S</u> <u>37-E</u> <u>NMPM</u>	
	12. County Lea	
16. Check	Appropriate Box To Indicate Nature of Notice, Report or Ot	her Data
NOTICE OF I		T REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON X REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMENT JOB	
	OTHER	[
OTHER	[_] ··	
17. Describe Proposed or Completed O	perations (Clearly state all pertinent details, and size pertinent data 1 1	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

The subject well was originally plugged and abandoned 5-11-53. The well was originally plugged as follows:

Open hole from TD of 10,800 3850'. Cement plug from 8 5/8" OD casing seat at 3850' to PBTD of 3695'. 8 5/8" OD casing shot off at #876' and pulled. Cement plug placed in top of 13 3/8" OD surface casing with appropriate marker.

Operator attempted to re-enter well by removing marker and drilling out 13 3/8" OD casing. Open hole was cleaned out with 11" OD bit to top of 8 5/8" OD casing stub found at 1938'. The 8 5/8" OD casing was entered and cleaned out to 2180' after finding several nitro shot holes in the 8 5/8". The bit left the casing at several places below the top with a great deal of red bed movement into the hole while making each connection. The hole will be abandoned after plugging by placing a cement plug at the top of the casing and replacing the dry hole marker as prescribed by NMOCC rules.

16. I hereby certify that the	ne information above is true and comp	plete to the best of my knowledge and belief.	
SIGNED MAL	Muno	TITLE Dect Mgr	DATE 2-24-72
APPROVED BY	Orig. Signed by Joe D. Remey		MAR 1 4 1972

CONDITIONS OF APPROVAL, IF ANY Dist. I, SUDY

OIL CONSERVATION COMM. HOBBS, N. M.

۰.

MAR 1 1070

RECEIVED