

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State ☐ Fee ☒

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Charles B. Gillespie, Jr.	8. Farm or Lease Name Gutman, et al
3. Address of Operator Box 1179, Midland, Texas 79701	9. Well No. 1
4. Location of Well UNIT LETTER A 990 FEET FROM THE North LINE AND 330' FEET FROM THE East LINE, SECTION 24 TOWNSHIP 24-S RANGE 37-E NMPM.	10. Field and Pool, or Wildcat Dollarhide, Queen
15. Elevation (Show whether DF, RT, GR, etc.) 3141.5 grd	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOB ☐
OTHER ☐

ALTERING CASING ☐
PLUG AND ABANDONMENT ☒

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 11103.

- 25 sx plugged across perforations from 3400 to 3800
- 4-1/2" casing shot off and pulled from 2983
- 25 sx plugged from 3050 to 2700
- 25 sx plugged from 2200 to 2090 (base of salt)
- 25 sx plugged from 451 to 351
- 10 sx plugged from 25' to 0
- 4' marker welded on side of 8-5/8 surface casing
- Fresh water mud 9.2# placed between all plugs
- Location levelled and junk removed

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Charles B. Gillespie, Jr. TITLE Operator DATE 4/3 /68

APPROVED BY [Signature] TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: _____

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

AUG 25 1 14 PM '65

5. Indicate Type of Lease
State ☐ Fee ☒

5. State Oil & Gas Lease No.

7. Unit Agreement Name

8. Farm or Lease Name

GUTMAN, et al

9. Well No.

1

10. Field and Pool, or Wildcat

Dollarhide, Queen

12. County

Lea

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator CHARLES B. GILLESPIE, JR.	3. Address of Operator Box 1179, Midland, Texas	4. Location of Well UNIT LETTER <u>A</u> <u>990</u> FEET FROM THE <u>North</u> LINE AND <u>330'</u> FEET FROM THE <u>East</u> LINE, SECTION <u>24</u> TOWNSHIP <u>24-South</u> RANGE <u>37-East</u> NMPM.	15. Elevation (Show whether DF, RT, GR, etc.) 3141.5 grd
--	--	--	--	---

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 25 sx plug will be placed across perforations at 3743-46 and 3764-70
- 4 1/2" casing will be shot off and pulled from 2200'
- 25 sx plug will be placed across the casing stub
- 25 sx plug will be placed at the base of the surface pipe at 401 and the open hole between this plug and the casing stub plug will be filled with heavy mud
- 10 sx plug will be placed in the top of the surface pipe and 4' marker will be welded on to the surface pipe.
- Location will be leveled
- Work will be commenced upon approval

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED

Charles B. Gillespie, Jr.

TITLE Operator

DATE 8-23-65

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: