

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE\*  
(Other instructions on  
reverse side)Form approved.  
Budget Bureau No. 42-R1424.

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. UNIT AGREEMENT NAME NMFU
2. NAME OF OPERATOR Continental Oil Company	8. FARM OR LEASE NAME JACK B 26
3. ADDRESS OF OPERATOR Box 460, Hobbs, N. Mexico 88240	9. WELL NO. 1
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 660' FNL & 1980' FWL, Section 26	10. FIELD AND POOL, OR WILDCAT Justis Blinberry
14. PERMIT NO.	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec 26 T-24S R-37E
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3209' OF	12. COUNTY OR PARISH LEA
	13. STATE N.M.

## 16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
(Other) Stimulate	<input checked="" type="checkbox"/>

## SUBSEQUENT REPORT OF:

WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
(Other) _____	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

It is proposed to stimulate the subject well with the following procedure:  
Tag for fill w/ tbg. If fill is above 5695' run bit & scraper & clean out to 5728'. Set retrievable pkr. at 5125'. Acidize w/ 3000 gal. paragon acid dispersion or equivalent. Flush tbg. w/ 22 bbls. of 20% KCL water w/ 1 gal/1000 gal. adomall. Swab back acid load. Poot w/ pkr. GIH w/ tbg. Set tbg. at 5661', SN at 5662' and mud anchor at 5693'. Run rods & pump and put back on production

18. I hereby certify that the foregoing is true and correct

SIGNED

John A. Butcherfield

TITLE

Admin. Supv.

DATE

6-7-77

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

APPROVED

JUN 9 1977

BERNARD MOROZ  
ACTING DISTRICT ENGINEER

\*See Instructions on Reverse Side

USGS (6), NMFU (4), File

RECEIVED

JUN 14 1977

CL CONSULTANT COMM  
FEBES, R. M.

67-2981A