(December 1989) DEPARTMEN	UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT		
SUNDRY NOTICES Do not use this form for proposals to dri Use "APPLICATION FO	#NM-14218 6. If Indian, Allottee or Tribe Name		
SUBMIT	7. If Unit or CA. Agreement Designation		
1. Type of Well         Oil       X         Well       X         Well       Other         2. Name of Ope ator <u>Texa co Exploration &amp; Produ</u> 3. Address and Telephone No.         P.O. Box 730, Hobbs, NM         4. Location of V/ell (Footage, Sec., T., R., M., or Survey D         Unit Letter J, 1980 FSL, 19         Section 26, T-24-S, R-37-1         12.       CHECK APPROPRIATE BOX(	88241-0730 (505) 393-7191 Description) 980 FEL,	8. Well Name and No. C.C. Fristoe B Fed NCT-2 9. API Well No. 30-025-1123 10. Field and Pool. or Exploratory Area Jalmat Yates 11. County or Parish. State Lea County, NM DRT, OR OTHER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION		
Subsequent Report	Abandonment Recompletion Plugging Back Casing Repair	Change of Plans Change of Plans New Construction Non-Routine Fracturing Water Shut-Off Conversion to Injection	
Final Abandonment Notice	Recompletion Report	s of multiple completion on Well Completion or	

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If give sub-surface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

## PROPOSED PROCEDURE

Inform BLM and OCD 24 hours prior to commencement of plugging.

- 1) MIRU, Install BOP. Rig up wireline.
- Perf 2 squeeze holes at 1100'. TIH w/ work string and tag CIBP at 2500' 2) 3)
- Load hole with salt gel mud; 10# brine and 25# gel/ Bbl. Pump 50', 10 s 4) class H cement on top of CIBP at 2500'.
- Establish circulation through squeeze perfs and fill casing and annulu with 405 sx. This includes 10% extra cement. Adjust volumes if needed. 5) POH. Fill casing and annulus from surface with 1" tubing if necessary. Cut off wellhead and install dry hole marker. Clean location.
- 6)
- Restore surface as per federal regulations. 7) 8)

(see reverse)

14. I hereby certify that the foregoing is true and correct Signed I If John Sow	Title	Engr. Asst.	_ Dale _7(24  91
This space for Formal or State office user Approved by Conditions of approval, if any:	Title		Date 8- 5- 91 /

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

A ..... 11.1.1

WELL DATA SHEET         Po- (5)           NC.         Lease:         C.C. Fristoe B Fed NCT-2         /1           Lx1980 FEL         Sec./Twn/Rng:         Unit J. Sec 26, T-24-S, R-37-E
---

	PLUG 7	IND ABANDON DATA	PO-113
OPERATOR: <u>Texac</u>	O E&P Inc.	LEASE: C.C. Fristoe B Federal NCT-2 #	(5/91)
FOOTAGE LOCATION	1000	DEADE: C.C. Fristoe B Federal NCT-2 #	1
LOCATION	: <u>1980 FSLx1980 FEL</u> Se	c./Twn/Rng: <u>Unit J. Sec 26, T-24-S, R-</u>	
<u>Casing integrity</u>	<u>tested 5-25-83, 600 psi</u>	/15 minutes - OK Lea County, New M	<u>27-E</u>
SCHEMATIC		Lea County, New M	exico
	ž	PLUGGING DATA	
Gr	3188' DF	Size 1100'-Surf. Cemented with 40	
		Includes 10% extra cement volume.	1
. 1000'	] 1100'-surface, 405 sx.	Class 'H' Cement, 1.18 cu ft/ sx	
. 1850'	TOC, Temp. survey	Intermediate Plug(s):	
. 2500'	CIBP, add 50' cem.	Size <u>None</u> Cemented with	sx. AUS (
. 2875	CIBP, 35' cement	Class 'H' cement, 1.18 cu ft/ sx Surface plug covers top of salt s CIBPs cover bace of the back of salt s	Action
. 3260		CIBPS cover base of salt section.	ection.
		Producing Zone Plugs:	
•		Size <u>CIBP, 35'</u> Cemented with	7sx.