

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT  
N. M. OIL CONS. COMMISSION  
O. BOX 1200  
DEEDS, NEW MEXICO 88240

FORM APPROVED  
Budget Bureau No. 1004-0135  
Expires: September 30, 1990

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals

5. Lease Designation and Serial No.  
Fed #NM-14218  
6. If Indian, Allottee or Tribe Name

SUBMIT IN TRIPLICATE

1. Type of Well  
☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator  
Texaco Exploration & Production Inc.

3. Address and Telephone No.  
P.O. Box 730, Hobbs, NM 88241-0730 (505) 393-7191

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)  
Unit Letter I, 1980 FSL, 660 FEL  
Section 26, T-24-S, R-37-E

7. If Unit or CA, Agreement Designation

8. Well Name and No.  
O.C. Fristoe B Fed NCT-2 #2

9. API Well No.  
30-025-11239

10. Field and Pool, or Exploratory Area  
Langlie Mattix SRQNGB

11. County or Parish, State  
Lea County, NM

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

| TYPE OF SUBMISSION                                    | TYPE OF ACTION                                  |                                                  |
|-------------------------------------------------------|-------------------------------------------------|--------------------------------------------------|
| <input type="checkbox"/> Notice of Intent             | <input checked="" type="checkbox"/> Abandonment | <input type="checkbox"/> Change of Plans         |
| <input checked="" type="checkbox"/> Subsequent Report | <input type="checkbox"/> Recompletion           | <input type="checkbox"/> New Construction        |
| <input type="checkbox"/> Final Abandonment Notice     | <input type="checkbox"/> Plugging Back          | <input type="checkbox"/> Non-Routine Fracturing  |
|                                                       | <input type="checkbox"/> Casing Repair          | <input type="checkbox"/> Water Shut-Off          |
|                                                       | <input type="checkbox"/> Altering Casing        | <input type="checkbox"/> Conversion to Injection |
|                                                       | <input type="checkbox"/> Other                  |                                                  |

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

9-3/4-91 Plug & Abandon well - see back for daily report

RECEIVED  
SEP 30 8 45 AM '91  
OIL & GAS  
ADMINISTRATIVE  
AREA

Approved as to part of well bore,  
Liability under bond is retained until  
surface restoration is completed.

14. I hereby certify that the foregoing is true and correct

Signed W. Johnson Title Engr. Asst. Date 9-27-91

(This space for Federal or State office use)

Approved by \_\_\_\_\_ Title \_\_\_\_\_ Date 10/14/91

Conditions of approval, if any:

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations in any matter within its jurisdiction.

✓  
RN  
E

# DASS OIL WELL SERVICING

INCORPORATED

TEXACO EXPLORATION & PRODUCTION - C.C. FRISTOE "B" NCT-2 - #2

9/3 - MOVE IN, RIG UP, PULL RODS AND TUBING LAYING DOWN, PICK UP WORK STRING AND TALLY IN HOLE WITH BIT AND SCRAPER TO 3225', PULL OUT OF HOLE, SHUT DOWN.

9/4 - RUN CAST IRON BRIDGE PLUG TO 3225', SET AND CIRCULATE MUD, SPOT 10 SACKS CEMENT FROM 3225' TO 3175', PULL UP HOLE TO 2400', SPOT 20 SACKS CEMENT FROM 2400' TO 2300', PULL UP HOLE TO 1304', SPOT 60 SACKS CEMENT FROM 1304' TO 1004', PULL TO 100', CIRCULATE 20 SACKS CEMENT FROM 100' TO SURFACE, CUT OFF WELLHEAD, PUT IN MARKER, FILL CELLAR WITH CEMENT, RIG DOWN AND MOVE OFF.

B.L.M.  
Steve Claffey 24-hr. notice - present location setting plugs  
2 - missed tags & plugs

505-392-6591 • P.O. BOX 2545 • HOBBS, NEW MEXICO 88241

LOCATIONS

HOBBS, NEW MEXICO (505) 392-6591  
ANDREWS, TEXAS (915) 523-4420  
EUNICE, NEW MEXICO (505) 394-2557  
MIDLAND, TEXAS (915) 685-6555