O. OF COPIES RECEIVED			Form C-103
	-	- a a B	Supersedes Old C-102 and C-103
DISTRIBUTION	- NEW ME	EXICOLDIE CONSERVATION COM	MISSION Effective 1-1-65
NTAFE			
LE		Jun 26 8 57 AM '67	5a. Indicate Type of Lease
s.G.5.		JUN EU O ST	State Fee.
AND OFFICE			5. State Oil & Gas Lease No.
PERATOR			
SUN	NDRY NOTICES AND	REPORTS ON WELLS TO DEEPEN OR PLUG BACK TO A DIFFERENT ORM C-101) FOR SUCH PROPOSALS.)	RESERVOIR.
USE **APPL	ICATION FOR PERMIT - " (F	ORM C-101) FOR SUCH PROPOSALS.	7. Unit Agreement Name
OIL GAS		[ang]i	e Mattix Woolwerth Unit Tract 1
WELL WELL	OTHER-		8. Farm or Lease Name
Name of Operator	1 Composetto	.	
	leum Corporation	ar .	9. Well No.
Address of Operator	Habba Mara Ma	ari aa	2
	- Hebbs, New Ma	XICO	10. Field and Pool, or Wildcat
Location of Well	000	Womth C	99 Ianglie Mattix
UNIT LETTER	FEET FROM	M THE North LINE AND	FEET FROM
	•	21.6	17E
THE West LINE, S	28	TOWNSHIP 248 RANGE	NMPM.
		CLL.L. DE DT CD	12. County
		ation (Show whether DF, RT, GR, etc.,	I.ca.
		3261 DF	
Che	ck Appropriate Box	x To Indicate Nature of Notic	ce, Report or Other Data
	F INTENTION TO:	1	SUBSEQUENT REPORT OF:
NOTICE	THE INTERVIOR		_
[-]	91.11	IG AND ABANDON REMEDIAL WORK	ALTERING CASING
REFORM REMEDIAL WORK	700	COMMENCE DRILL	ING OPNS. PLUG AND ABANDONMENT
EMPORARILY ABANDON			
			S ACMENT ION 1
JLL OR ALTER CASING	CHA	1102 . 27.110	CEMENT JOB
JLL OR ALTER CASING	СНА	1102 . 27.110	CEMENT JOB
OTHER		OTHER	
7. Describe Proposed or Complet work) SEE RULE 1103.	ted Operations (Clearly st	other	tinent dates, including estimated date of starting any propose
Describe Proposed or Complet work) SEE RULE 1103. Palled reds, OH 33541 to 3	pump and tubing	other	3532 to 3593, Water fraced osa water, 15,000 10-20 sand, H to 3593 Ran tubing, reds
Describe Proposed or Complet work) SEE RULE 1103. Palled reds, OH 3354 to 200% Moth baland pump and	pump and tubing 3593 with 15,00 11s and 400# Rec resumed pumping	g. Cleaned out OH from Ogals. Gelled Santa R	a 3532 to 3593, whiter fraced osa water, 15,000 10-20 sand, H to 3593. Ran tubing, reds icing status.
Describe Proposed or Complet work) SEE RULE 1103. Palled reds, OH 3354 to 200% Moth baland pump and	pump and tubing 3593 with 15,00 11s and 400# Rec resumed pumping	g. Cleaned out OH from OO gals. Gelled Santa Rek Salt. Cleaned out Og. No change in produ	a 3532 to 3593, water fraced osa water, 15,000 10-20 sand, H to 3593. Ran tubing, reds icing status.