


(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Las Cruces

Lease No. 032326 (a)

Unit 4.4.2.2



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL	<u>Subsequent Report of Plug Back</u>	<u>X</u>

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Jack A-29 No. 3

Hobbs, New Mexico February 28, 1951

Well No. 3 is located 1970 ft. from N line and 330 ft. from E line of sec. 29
NE/4 Sec. 29 24S 37E N.M.P.M.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Langlie-Mattix Lon New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 3279 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Jack A-29 No. 3 was recompleted as a Yates gas well as follows:

A retainer was set at 3386' and cemented with 125 sacks cement. Gun perforated 7" casing from 3006' to 3056', 3066' to 3121', and from 3131' to 3181'. On initial potential flowed 730 MCF gas in 24 hours from the Yates formation with a shut in pressure of 945.2 psi.

Workover commenced 5-12-50.

Workover completed 5-16-50.

Date completion test 5-29-50.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Continental Oil Company

Address Box 63

Hobbs, New Mexico

By E. L. Shaper
Title District Superintendent

Report of
the
Board of
Directors

Section 101 of the
Internal Revenue Code

Section 102 of the
Internal Revenue Code

101	102	103	104	105	106	107	108	109	110
111	112	113	114	115	116	117	118	119	120
121	122	123	124	125	126	127	128	129	130
131	132	133	134	135	136	137	138	139	140
141	142	143	144	145	146	147	148	149	150

Page 1

Section 101 of the Internal Revenue Code

Section 102 of the Internal Revenue Code

Section 103 of the Internal Revenue Code

Section 104 of the Internal Revenue Code

Section 105 of the Internal Revenue Code