NO COPIES RECEIVED	Form C-103 Supersedes Old
	C-102 and C-103
	Effective 1-1-65
	5a. Indicate Type of Lease
DFFICE	State Fee X
OR III	5. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS	
SUNDRY NOTICES AND REPORTS ON WELLS to not use this form for proposals to drill or to deepen or plug back to a different reservoir. use "application for permit -" (form C-101) for such proposals.)	
	7. Unit Agreement Name
WELL CAS WELL OTHER-	8. Farm or Lease Name
ame of Operator	William H. Harrison "A"
Atlantic Richfield Company 3. Address of Operator	9. Well No.
P. O. Box 1710, Hobbs, New Mexico 88240	2
4. Location of Well	10. Field and Pool, or Wildcat
UNIT LETTER D 660 FEET FROM THE North LINE AND 660 FEET FROM	
UNIT LETTER , FEET FROM THE LINE AND FEET FROM	
THE West LINE, SECTION 29 TOWNSHIP 24S RANGE 37E NMPM.	
	<i></i>
15. Elevation (Show whether DF, RT, GR, etc.)	12. County
<u>AIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIII</u>	Lea Allilli
^{16.} Check Appropriate Box To Indicate Nature of Notice, Report or Oth	ier Data
NOTICE OF INTENTION TO: SUBSEQUENT	REPORT OF:
	٦
PERFORM REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	
OTHER	
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE RULE 1903.	estimated date of starting any proposed
 TD 3650'. Completed OH 3356-3650'. Propose to clean out, test in an attempt to restore to production in Rivers Queen as follows: 1. Rig up, install BOP. 2. MOH w/6¼" bit on tbg, check for fill up. 3. Clean out to TD w/foam. 4. Run completion assy & set @ approx 3620'. 5. Swab test & return to production same zone. 	the Langlie Mattix Seven
18. I hereby certify that the information above is true and complete to the bast of my cowledge of	
signed Dist. Drlg. Supv.	5/28/75
	n and a state of the
APPROVED BY	DATE
CONDITIONS OF APPROVAL, IF ANY:	

•