

L CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

0+5-NMOCD-Hobbs

1-Foreman-CK

1-File

1-Engr JIM

5a. Indicate Type of Lease

State ☐Fee ☒

5. State Oil & Gas Lease No.

SUNDY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name W. Dollarhide Drinkard
2. Name of Operator Getty Oil Company	8. Farm or Lease Name W. Dollarhide Drink. Uni
3. Address of Operator P.O. Box 730, Hobbs, N.M. 88240	9. Well No. 64
4. Location of Well UNIT LETTER I, 1990 FEET FROM THE South LINE AND 660 FEET FROM THE East LINE, SECTION 31 TOWNSHIP 24S RANGE 38E NMPM.	10. Field and Pool, or Wildcat Dollarhide Drinkard
15. Elevation (Show whether DF, RT, GR, etc.) 3138' DF	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Rig up pulling unit and install B.O.P.
2. TIH with 4 3/4" bit and drill out EZ drill retainer at 2802'.
3. Drill cement ± 5775 to landing collar.
4. Run 4" FL-4S 6600' to surface cement with 400 sxs. class "C".
5. Perforate lower Drinkard 6256-6479'.
6. Acidize with 10-12,000 gallons retarded 15% HCl.
7. Run tubing and rods.
8. Place well on test.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED

Dale R. Crockett

TITLE Area Superintendent

DATE 8/19/82

ORIGINAL SIGNED BY

JERRY SEXTON

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY

DISTRICT 1 SUPR.

AUG 24 1982