

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No. -----
7. Unit Agreement Name -----
8. Farm or Lease Name J. W. Sherrell
9. Well No. 5
10. Field and Pool, or Wildcat Jalmat (Yates)
12. County Lea

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT --" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER- 2. Name of Operator Skelly Oil Company 3. Address of Operator P. O. Box 1351, Midland, Texas 79701 4. Location of Well UNIT LETTER N 4290 FEET FROM THE North LINE AND 3106 FEET FROM THE East LINE, SECTION 31 TOWNSHIP 24S RANGE 37E NMPM. 15. Elevation (Show whether DF, RT, CR, etc.) 3244' DF
--

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER Plugback to base of Yates formation <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

This well is an open-hole completion. To insure against producing from the interval to be included in the proposed Langlie-Jal Unit, the following work was done:

1. Moved in and rigged up workover rig 9-30-70.
2. Ran steel measuring line, found cavings at 2853'.
3. Ran sand pump and cleaned out from 2853 to TD 3350'.
4. Ran McCullough Gamma Ray Neutron Log; found top of Seven Rivers at 3008'.
5. Set open-hole plug at 3030', dumped pea gravel to 3016' and Hydromite to 3000'.
6. Ran 2-3/8" OD tubing and swabbed well dry.
7. Hooked Yates to gas sales line and returned to producing status on October 3, 1970, producing 323 MCF per day from Yates open-hole Section 2720-3000'.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED (Signed) J. R. Avent	TITLE Dist. Adm. Coordinator	DATE Oct. 8, 1970
APPROVED BY [Signature]	TITLE [Signature]	DATE [Signature]
CONDITIONS OF APPROVAL, IF ANY:		