

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO. 30-025-11302
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name LANGLIE JAL UNIT
8. Well No. # 28
9. Pool name or Wildcat LANGLIE MATTIX
10. Elevation (Show whether DF, RKB, RT, GR, etc.)

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator MERIDIAN OIL INC.
3. Address of Operator P.O. Box 51810, Midland, TX 79710-1810
4. Well Location Unit Letter <u>O</u> : <u>1900'</u> Feet From The <u>EAST</u> Line and <u>440'</u> Feet From The <u>SOUTH</u> Line

Section 31

Township 24S

Range 37E

NMPM LEA

County

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ADD SEVEN RIVERS ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

2/15/94: MIRU. POOH W/PMP AND RODS. POOH E/TBG.
2/16/94: PU WORKSTRING. RIH TO 3477. PU POWER SWIVEL. CLEANED FILL AND JUNK TO 3505. DRILD NEW HOLE 3505-3530. CIRC. OUT. POOH W/STDS
2/17/94: RIH TO 3485. TAGGED ON BRIDGE. RU POWER SWIVEL. WASHED AND REAMED TO 3530. DRILG NEW HOLE 3530-3552. POOH. TIH TO 3350
2/18/94: WASHED AND REAMED TO BOTTOM. DRILLED NEW HOLE TO 3560. CIRC CLEAN. MADE SHORT TRIP. CLANED OUT BRIDGES AT 3420 & 3480. CIRC WELL CLEAN. POOH W/STDS. WAITED 1 HR. RIH. CLEANED OUT BRIDGES AT 3440. & 3480. CIRC. WELL. POOH. MIRU WIRELINE. RAN GAUGE RING TO 3420. SAT DOWN ON BRIDGE. POOH. LD GAUGE RING. PU AND RIH W/CIBP. SET AT 3370. RD WIRELINE. FILLED HOLE W/FW. SHUT RAMS AND TRIED TO TEST. PMPED AT 400 PSI.
2/19/94: RU SCHLUMBERGER. SET PKR AND RIH TO 3203. SET PKR. LOADED TBG W/FW. PMPED. LOADED ANNULUS W/FW. RIH TO 3298. SET PKR. PMPED DOWN TBG. RIH W/PKR TO 3360. SET PKR AT 3360. LOADED ANNULUS. RESET PKR AT 3329. PRES TO 500 PSI. HELD OK. RELSD PKR & POOH. LD PKR. RIH. SPOTTED 25 SXS 'C' W/2% CACL. POOH

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Donna Williams TITLE PRODUCTION ASSISTANT DATE 2/28/94

TYPE OR PRINT NAME DONNA WILLIAMS

TELEPHONE NO. 915-688-6943

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

MAR 04 1994

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: