

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.  
30-025-11303

5. Indicate Type of Lease  
STATE ☐ FEE ☒

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:  
OIL WELL ☒ GAS WELL ☐ OTHER

2. Name of Operator  
MERIDIAN OIL INC.

3. Address of Operator  
P.O. Box 51810, Midland, TX 79710-1810

4. Well Location  
Unit Letter G : 1977' Feet From The EAST Line and 2310' Feet From The NORTH Line

Section 31

Township 24S

Range 37E

NMPM LEA

County

10. Elevation (Show whether DP, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: ADD SEVEN RIVERS ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

5/9/94: MIRU. POOH W/RODS AND PMP. ND WH NU BOP. POH W/TBG.  
5/10/94: RIH W/BIT AND DC AND TAG AT 3486'. CHARGE UP FORMATION W/WATER AND WASH AND DRILL TO 3547. CIRC CLEAN.  
5/11/94: RIH AND TAG UP AT 3497. LOAD HOLE AND DRILL AND WASH TO 3510'. PULL UP TO 3480 AND CIRCULATE CLEAN. POH W/BIT AND RU WEDGE WIRELINE AND RUN GR/COR LOGS TO 3486 TO 1785. SET CIBP AT 3385. LOAD HOLE W/WATER. PMP.  
5/12/94: RIH W/GUIBERSON UNI PKR AND TAG CIBP AT 3385 AND SET PKR AT 3374. MOVE PKR AT 3312. SET PKR AT 3281.  
5/13/94: SWAB TEST AND POH W/PKR. RIH W/BIT AND DC. DRILL CIBP AT 3385 AND CHASE TO PBTD AT 3486. POH AND LD DC AND BIT. TURN TO PRODUCTION

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE PRODUCTION ASSISTANT

DATE 5/19/94

TYPE OR PRINT NAME

Dore Williams

TELEPHONE NO. 915-688-6943

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON  
DISTRICT I SUPERVISOR

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE MAY 20 1994

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

APR 20 1994

DOJ  
OFFICE