

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 South First, Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

JAN 17 2001

Form C-103
Revised March 25, 1999

OIL CONSERVATION DIVISION
2040 South Pacheco
Santa Fe, NM 87505

WELL API NO. 30-025-11308
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-148-18
7. Lease Name or Unit Agreement Name: LANGLIE JAL UNIT
8. Well No. 10
9. Pool name or Wildcat Langlie Mattix (SRQBG)

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
Oil Well ☐ Gas Well ☐ Other Water Injection Well

2. Name of Operator
PHOENIX HYDROCARBONS OPERATING CORP.

3. Address of Operator
P O Box 3638, Midland TX 79702

4. Well Location
Unit Letter E : 1980 feet from the north line and 660 feet from the west line

Section 32 Township 24S Range 37E NMPM Lea County NM

10. Elevation (Show whether DR, RKB, RT, GR, etc.)
3254' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

11-19-02 Notify OCD; MIRU; Dig & line working pit; NU BOP; RIH & spot 35 sxs @ 3405' - 3215' and tag; POOH; WOC.

11-20-02 RIH & tag @ 3215'; Circ 10# mud; POOH & spot 20 sxs cmt @ 2914' - 2795'; POOH & spot 20 sxs @ 1104' - 985'; POOH & spot 20 sxs @ 460' - 295'; WOC; RIH & tag @ 295'; POOH spot 10 sxs @ 60' to surface; RD & cut off wellhead and anchors; install dry hole marker; level pit and cellar; Move out.

Approved as to Plugging of the Well Bore.
Liability under bond is retained until
Surface restoration is completed.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Phyllis R. Gunter TITLE Agent

Type or print name Phyllis R. Gunter

(This space for State use)

Telephone No 915/686-9869

APPROVED BY
Conditions of approval, if any:

ORIGINAL SIGNED BY
GARY W. WALK
OC FIELD REPRESENTATIVE II/STAFF MANAGER

DATE DEC 13 2002

GWW