

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 South First, Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87504

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87504

Form C-103
Revised March 25, 1999

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well ☐ Gas Well ☐ Other Water Injection Well ☐	WELL API NO. 30-025-11308
2. Name of Operator KENSON OPERATING COMPANY INC.	5. Indicate Type of Lease STATE ☒ FEE ☐
3. Address of Operator P O BOX 3531, MIDLAND TX 79702	6. State Oil & Gas Lease No. B-148-18
4. Well Location Unit Letter <u>E</u> : 1980 feet from the <u>north</u> line and 660 feet from the <u>west</u> line Section <u>32</u> Township <u>24S</u> Range <u>37E</u> NMPM LEA County <u>NM</u>	7. Lease Name or Unit Agreement Name: LANGLIE JAL UNIT
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3254' GR	8. Well No. 10
	9. Pool name or Wildcat LANGLIE MATTIX (SRQBG)

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

- PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

- REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

- 3464' - 3310'
1. Fill open hole 3526 to 3414 w/100' cement plug (tag).
2. Spot 50' plug across 7" casing shoe @ 3414' (tag).
3. Set CIBP @ 3300' and dump 25 sx of cement.
4. Displace hole w/MLF 9.5# brine 25# gel.
5. Spot 100' plug across base of salt @2900'.
6. Spot 100' plug across top of anhydrite @ 1100'.
7. Spot 100' plug across 9-5/8/7" shoe @ 458' to 358' (tag).
8. 10 sx surface plug 0-10'. Install dry hole marker.

THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE M. A. Sirgo TITLE ENGINEER

DATE 6-4-02

Type or print name M. A. SIRGO, III

Telephone No 915/685.0878

APPROVED BY _____

Conditions of approval, if any: _____

ORIGINAL SIGNED BY

GARY W. WINK

DATE _____
CC FIELD REPRESENTATIVE II/STAFF MANAGER

JUN 06 2002

PLUGGING & ABANDONMENT WORKSHEET

(2 STRING CSNG)

OPERATOR KENSON OPERATING COMPANY INC.

LEASENAME LANGLEE JAL UNIT

WELL # 10 (3254 GR)
 SECT 32 TWN 24S RNG R37E
 FROM 1980 N/S L 660 E/W L
 TD: 3549 FORMATION @ TD Queen
 PBDT: 3526 (Junk) FORMATION @ PBDT Queen

9-5/8"
@ 408
TOC Surf
 834' Sqz'd
 913' 535 sx
 2906' Sqz'd
 3074' 610 sx
 3360' perfs.
 3397' 7"
@ 3414'
TOC ?
 300 sx
 (5-1939)

	SIZE	SET @	TOC	TOC DETERMINED BY
SURFACE	9-5/8"	408'	Surf	Circulation
INTMED 1				
INTMED 2				Orig 300 sx Sqz'd
PROD	7"	3414'	?	w/1145 sx
	SIZE	TOP	BOT	TOC DETERMINED BY
LINER 1				
LINER 2				
	CUT & PULL @		TOP - BOTTOM	
INTMED 1			PERFS	3360 - 3397
INTMED 2			OPENHOLE	3414 - 3526
PROD	0			

*REQUIRED PLUGS DISTRICT I

RUSTLER (ANHYD)	1110
YATES	2906
QUEEN	3495
GRAYBURG	
SAN ANDRES	
CAPTAIN REEF	
DELAWARE	
BELL CANYON	
CHERRY CANYON	
BRUSHY CANYON	
BONE SPRING	
GLORIETA	
BLINEBRY	
TUBB	
DRINKARD	
ABO	
WC	
PENN	
STRAWN	
ATOKA	
MORROW	
MISS	
DEVONIAN	

PLUG	TYPE PLUG	SACKS CMNT	DEPTH
EXAMPLES			
PLUG #1	OH	35 SXS	6400'
PLUG #2	SHOE	50 SXS	5350'-5450'
PLUG #3	CIBP/35'		4800'
PLUG #3	CIBP	25 SXS	4800'
PLUG #4	STUB	50 SXS	3600'-3700'
PLUG #5	RETNR SQZ	200 SXS	400'
PLUG #6	SURF	10 SXS	0-10'
PLUG #1	OH	100'	3414' Top
PLUG #2	Shoe	50'	3364' Top
PLUG #3	CIBP		3300'
PLUG #4	CIBP	25 sx	3300'
PLUG #5	Salt	100'	2900'
PLUG #6	Anhy	100'	3100'
PLUG #7	Shoe	100'	458-358'
PLUG #8	Surf	10 sx	0-10'
PLUG #9			
PLUG #10			
PLUG #			
PLUG #			
PLUG #			
PLUG #			
PLUG #			
PLUG #			
PLUG #			
PLUG #			
PLUG #			
PLUG #			

TD 3549'

3526' Junk
 PBDT
 3549'
 TD