

## CONSERVATION DIVISION

P O BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

AS BY LETTER RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-	7. Unit Agreement Name
2. Name of Operator	8. Farm or Lease Name
Lewis B. Burleson, Inc.	Woolworth
3. Address of Operator	9. Well No.
P.O. Box 2479, Midland, Texas 79702	1
4. Location of Well	10. Field and Pool, or Wildcat
UNIT LETTER <u>K</u> <u>2310</u> FEET FROM THE <u>West</u> LINE AND <u>1650</u> FEET FROM	Jalmat
THE <u>South</u> LINE, SECTION <u>33</u> TOWNSHIP <u>24S</u> RANGE <u>37E</u> N.M.P.M.	
11. Elevation (Show whether DF, RT, GR, etc.)	12. County
3247'DF	Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

We request your approval to plug this well in the following manner:

1. Set Bridge plug with cement cap on top of fish which we were unable to recover at 2500 feet, which is at base of the salt.
2. Fill hole with mud to 900 feet.
3. Cut 5½" casing and set plug 50 feet in and out of stub at same depth of surface casing being 850 feet.
4. 10' plug in top of surface pipe with markers with mud between plugs.

You will be notified in sufficient time to witness this operation.

Land will be put back to original contour so we can have final inspection.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED JLB TITLE President DATE August 12, 1982ORIGINAL SIGNED BY  
JERRY SEXTONAPPROVED BY DISTRICT 1 SUPR.  
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

AUG 18 1982