1625 N. French Dr. Husbs, NM 88240

Form	3160-5
(June	1990)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED			
Budge	t Bureau N	o. 10	04-0135
Exp	ires: Marc	h 31,	1993

BUREAU OF LAND MANAGEMENT		5. Lease Designation and Serial No.
Do not use this form for proposals to d	Irill or to deepen or reentry to a different reservoir. OR PERMIT—" for such proposals	LC-032874 6. If Indian, Allottee or Tribe Name
		7. If Unit or CA, Agreement Designation
	T IN TRIPLICATE	
1. Type of Well Gas		8. Well Name and No.
XX Well Well Other 2. Name of Operator		G.L. Erwin "A" Fed
Texaco Exploration & Pro	oduction, Inc.	9. API Well No.
3. Address and Telephone No.		30-025-11356
P. O. Box 3109, Midland, TX 79702 4. Location of Well (Footage, Sec., T., R., M., or Survey Description)		10. Field and Pool, or Exploratory Area Justis - Blinebry
Unit Letter N, 330' FSL		Tubb Brinkard II. County or Parish, State
Sec. 35', Township 24 -		
	-,	Lea - New Mexico
2. CHECK APPROPRIATE BOX	(s) TO INDICATE NATURE OF NOTICE, REPOR	RT, OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTION	
Notice of Intent	Abandonment	Change of Plans
Subsequent Report	Recompletion	New Construction
Subsequent Report	Plugging Back Casing Repair	Non-Routine Fracturing Water Shut-Off
Final Abandonment Notice	Altering Casing	Conversion to Injection
	Other	Dispose Water
		(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)
give subsurface locations and measured and true vertice	Il pertinent details, and give pertinent dates, including estimated date of starting all depths for all markers and zones pertinent to this work.)*	
1. Set 2 7/8" CIBP @ 700	0', (Devonian) fill 2 7/8" csg v	v/ 120 sx plug
7000'-2400' W.O.C. Ta 2. Set 2 7/8" CIBP @ 570	ng @ 2365'	/
5700'-2400' W.O.C. Ta	0' (Blinebry) fill 2 7/8" csg w	v/85 sx plug
3. Set 2 3/8" CIBP @ 505	0' (Drinkard) fill 2 3/8" csg w/	70 sx plua
5050'-2400' W.O.C. Ta	.g @ 2386'	Fag
4. Cut all 3 csg strings 5. Spot 75 sx plug 2386'	2386'-2200' L/D csgs	<u>.</u>
6. Displace hole w/MLF 9	-2200' (Stub) No Tag Respot 75 s .5# brine w/25# gel P/BBL	x Tag @ 2115'
7. Perf 6 holes @ 1500',	(9 5/8") csg sqz w/125 sx plug	1500'-1200' (T-salt)
1ag @ 1105		
8. Perf 6 holes @ 310' (9 5/8" csg) sqz 125 sx plug 310'	-200' (13 3/8" shoe)
W.U.C. Tag @ 184'		
J. CIIC CMC JU -Bull W/	5 sx - Install dry hole marker.	
	Approved as to play they will bore. Liability under bond to retain ad until surface restoration is competed.	7
14. I hereby certify that the foregoing is true and correct		
Signed Jumphan OVED	Title_MANAGER	Date 5/8/0/
(This space for Federal or State office use)		Date -/ J
Approved by ORIG. SGD.) DAVID R.	ALASS Title	Date
Conditions of approva, if a WAY 2 9 2001		

IMPRACTAL CAND MANTE

E1:6 MA 25 YAM 1005

BECEINED