

RECEIVED AUGUST 21, 1965

71-032874 - a

SUNDAY NOTICES AND REPORTS ON WELLS

1. ☒ USE ☒ CALL ☐ NO ☐ WELL ☐ OTHER		2. DATE OF OPERATION Texaco Inc		3. NAME OF OPERATOR Texaco Inc		4. ADDRESS OF OPERATOR P.O. Box 720 - Hobbs, NM 88240		5. LOCATION OF WELL (Report location clearly and in accordance with any state requirements. See also space 17 below.) At surface 1650' FSL 2310' FWL UNIT LETTER K SEC 35 T24S R37E		6. FIELD AND POOL, OR WELLS JUSTIS BLINERY, JUSTIS TMS DECA JUSTIS DEWONIAN, N		7. DATE OF WELL OR FIELD OR POOL OR AREA K, Sec 35 T24S R37E		8. DEPTH OF WELL 3182 DF		9. DEPTH OF FIELD LEA		10. DEPTH OF POOL NM	
---	--	---	--	--	--	---	--	---	--	---	--	--	--	------------------------------------	--	---------------------------------	--	--------------------------------	--

28. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBJECT: LITTON 02:

TEST WATER SHUT-OFF	☐	PULL OR ALTER CASING	☐	WATER SHUT-OFF	☐	REPAIRING WELL	☐
FRACTURE TREAT	☐	MULTIPLE COMPLETE	☐	FRACTURE TREATMENT	☐	ALTERING CASING	☐
SHOOT OR ACIDIZE	☐	ABANDON*	☒	SHOOTING OR ACIDIZING	☐	ABANDONMENT*	☐
REPAIR WELL	☐	CHANGE PLANE	☐	(Other) _____			

(NOTE: Report results of multiple completions on Well Completion or Fracturing Report and Log-Form.)

17. DESIGN/TYPE PROPOSED OR COMPLETE OPERATIONS: (Clearly state all pertinent details, and give pertinent data including estimated date of starting any proposed work. If well is directionally drilled give subsurface locations and measured and true vertical depths for all markers and zones pertinent to the work.)

Subject wellbore consists of 3 strings of 2 $\frac{7}{8}$ " csg

- (1) Rig up on Devonian csg string set CIBP @ 000' cap w/ 35' cnt, set CIBP @ 5260' cap w/ 35' cnt, set CIBP @ 3950' cap w/ 35' cnt.
- (2) Rig up on Tubb Drinkard string set CIBP @ 5260' cap w/ 35' cnt, set CIBP @ 3950' cap w/ 35' cnt.
- (3) Rig up on Blinbery string, set CIBP @ 3950' cap w/ 35' cnt
- (4) Run Sree part, cut off Blinbery, Tubb Drinkard, and Devonian csg strings as deep as possible, pull each casing string.
- (5) Spot 100' cnt plug immediately above cut off casing string's
- (6) Spot 100' cnt plug from 3490 - 3590', across intermediate casing shoe
- (7) Spot 100' cnt plug from 1000 - 1100', across top of salt
- (8) PerS sqz hole in csg @ 325', set cnt retainer @ 225', circ cnt out broadenhead, sqz 50sx around surface casing shoe
- (9) Spot 10' surface plug, install dry hole marker, clean and blade location

I hereby certify that the foregoing is true and correct

SIGNATURE**TITLE**

DATE _____

(THIS SPACE FOR FEDERAL OR STATE OFFICE USE)

CONDITIONS OF APPROVAL IF ANY:

TITLE

DATE _____

***See Instructions on Reverse Side**

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States an "false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction."