

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY RECEIVED

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

BUR. OF LAND MGMT
ROSWELL DISTRICT

1. oil well ☒ gas well ☐ other ☐

2. NAME OF OPERATOR
TEXACO Inc.

3. ADDRESS OF OPERATOR
P.O. Box 728, Hobbs, New Mexico 88240

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 1650' FSL & 2310' FWL
AT TOP PROD. INTERVAL: (Unit Letter 'K')
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF	<input type="checkbox"/>	<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>	<input type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	<input type="checkbox"/>
PULL OR ALTER CASING	<input type="checkbox"/>	<input type="checkbox"/>
MULTIPLE COMPLETE	<input type="checkbox"/>	<input type="checkbox"/>
CHANGE ZONES	<input type="checkbox"/>	<input type="checkbox"/>
ABANDON*	<input type="checkbox"/>	<input type="checkbox"/>
(other) Triple Downhole Commingle		

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

* Justis Blinebry
Justis Devonian, North
Justis Tubb Drinkard

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. Rigged up. Kill Well.
2. Clean out well.
3. Set RBP in Blinebry string @ 5660'. Acidize 2 7/8" Blinebry perfs. 5293-5631 W/3000 gals. 15% NEEE Acid in 3-stages using 250# rock salt between stages. Flush W/ produced water.
4. Set 2 7/8" csg. plug @ 200' in Tubb-Drinkard string.
5. Set 2 7/8" csg. plug @ 200' in Devonian Zone.
6. Test all strings to 2000#. Tested OK. Pull plugs from all strings.
7. Install pumping equipment.
8. on 24 hrs. potential test ending 12-1-83, well pumped a 0 Bbls. oil 39 Bbls water & 11 MCF. Well completed triple downhole commingle, Justis Blinebry, Justis Devonian, North, and Justis Tubb Drinkard.

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED [Signature] TITLE Asst. Dist. Mgr. DATE 12-5-83

ACCEPTED FOR RECORD (This space for Federal or State office use)

APPROVED BY [Signature] TITLE _____ DATE _____

CONDITIONS OF APPROVAL IF ANY
MAY 8 1984

[Signature]

ROSWELL, NEW MEXICO *See Instructions on Reverse Side

RECEIVED

MAY 9 1984

C.C.D.
HOBBS OFFICE