

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Form approved,
General Bureau No. 42 R1424.
5. LEASE, SUBLEASE, AND SERIAL NO.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to complete or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐		7. UNIT AGREEMENT NAME	
2. NAME OF OPERATOR		8. FARM OR LEASE NAME	
3. ADDRESS OF OPERATOR		9. WELL NO.	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface		10. FIELD AND POOL, OR WILDCAT	
14. PERMIT NO.		12. COUNTY OR PARISH	
15. ELEVATIONS (Show whether DP, RT, GR, etc.)		13. STATE	

TEXACO Inc.
P. O. Box 728, Hobbs, New Mexico 88240
Well is located 1650' from the South Line and 2310' from the West Line of Section 35, T-24-S, R-37-E, Lea County, New Mexico.
Regular 3182' (D. F.)
Lea New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	☐	WATER SHUT-OFF	☒
PULL OR ALTER CASING	☐	REPAIRING WELL	☐
MULTIPLE COMPLETE	☐	ALTERING CASING	☐
ABANDON*	☐	ABANDONMENT*	☐
CHANGE PLANS	☐	(Other)	☐

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

THE FOLLOWING WORK HAS BEEN COMPLETED ON SUBJECT WELL:

1. Pull Rods and pump.
2. Perforate 2 7/8" od casing w/1 JSPF from 5293' to 5315' and w/1 JSPI @ 5320', 5326', 5335', 5349', 5356', 5374', 5380'.
3. Set RBP @ 5425'.
4. Acidize new perforations w/ 3000 gals. 15% NE acid in 15 equal stages w/ 2 Ball Sealers between stages.
5. Frac perforations w/ 24,000 gals. gelled lease crude carrying 1# sand and 1/40# Adomite per gal. in 3 equal stages w/ 10 Ball Sealers between stages.
6. Swab, Test, and return to production.

18. I hereby certify that the foregoing is true and correct

SIGNED [Signature] TITLE Assistant District Superintendent DATE December 10, 1968

(This space for Federal or State office use)

APPROVED BY [Signature] TITLE Assistant District Superintendent DATE December 10, 1968

CONDITIONS OF APPROVAL, IF ANY: