Foria	9-331
(May	1963)

16.

## UNI O STATES SUBMIT IN TRIPLIOR (Other instructions verse side)

GEOLOGICAL SURVEY

.Е.

Form approved. Budget Bureau No. 42-R1424. 5. LEASE DESIGNATION AND SERIAL NO.

LC-057509

SUNDRY	NOTICES	AND	<b>REPORTS</b>	NO	WELLS

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

H.M.

	(De not use this form for proposa Use "APPLICA"	is to drill or to deepen or plug back to a different reservoir. TON FOR PERMIT—" for such proposals.)	
1.	OIL GAS OTHER		7. UNIT AGREEMENT NAME
2.	NAME OF OPERATOR		8. FARM OR LEASE NAME
	TEXACO INC.		G. L. Erwin 'B' Fed NCT-2
3.	ADDRESS OF OPERATOR		9. WELL NO.
	P.O. Box 728, Hobb	os, New Mexico 88240	4
4.	See also space 17 below.)	arly and in accordance with any State requirements.*	10. FIELD AND POOL, OR WILDCAT 1. JUSTIS-Dev; Justis Bl.;
	At surface  330' from South Line &	1650' from East Line of	Justis Tubb-Drk: M Justis 11. SEC., T., E., M., OR BLE. AND SURVEY OR AREA FUSSElma
	Sec 35, T-24-S, R-37-E,		SURVEY OR AREA FUSSELMA
	•	•	Sec 35, T-24-S, R-37-E
14	. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.)	12. COUNTY OR PARISH 13. STATE

3180 DF Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

TEST WATER SHUT-OFF PULL OR ALTER CASING WATER SHUT-OFF REPAIRING WELL	NOTI	CE OF INTENTION TO:	SUBSEQUENT REPORT OF:		
FRACTURE TREAT  SHOOT OR ACIDIZE  REPAIR WELL  (Other)  MULTIPLE COMPLETE  FRACTURE TREATMENT  SHOOTING OR ACIDIZING  SHOOTING OR ACIDIZING  (Other)  ABANDONMENT*  (Other)  FRACTURE TREATMENT  ALTERING CASING  (Other)  SHOOTING OR ACIDIZING  (Other)  COMPLICATION  (NOTE: Report results of multiple completion on Well  Completion or Recompletion Report and Log form.)	FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL	MULTIPLE COMPLETE ABANDON*	FRACTURE TREATMENT SHOOTING OR ACIDIZING ABANDONMENT*  (Other) Downhole Commingle		

- 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*
  - 1. Rig up. Kill well.

Regular

- Perforate 2 7/8" OD csg in Tubb-Drinkard zone from 7038' 7042' w/4 JSPF. Job complete 7-24-75.
- All zones downhole commingled. 3.

8. I hereby certify that the foregoing by true and correct		
SIGNED	TITLE .	Assistant District Supting 3-6-75
(This space for Federal or State office use)	TITLE	ACCEPTED FUN ILLU
CONDITIONS OF APPROVAL, IF ANY:		AUG I - NO SURVEY  U. S. GEOLOGICAL SURVEY  W. S. GEOLOGICAL SURVEY  NEW MEXICO
		U. S. GEOD NEW MEXIL

\*See Instructions on Reverse SideOBE