

(Nov. 1936)

Indian Agency.....

(SUBMIT IN TRIPLICATE)

U. S. Land Office **Las Cruces**Lease or permit No. **032874****Geo. L. Erwin (a)**

Allottee.....

**UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY**

Lease No.....

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....		SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	<input checked="" type="checkbox"/>	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....		SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....		SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....		SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

DUPLICATE

Wink, Texas, May 13, 1938

Well No. **2** is located **1980** ft. from **S** line and **330** ft. from **W** line of sec. **35**

NW 1/4 SW 1/4 Sec. 35 **24-S** **37-E** **N.M.P.M.**
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)

Mattix Area **Lea County** **New Mexico**
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is **3185** ft. **Approx.**

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

T. D. 75' - sand.

Set and mudded 75' of 15½" casing at 75', 5-8-38.

Pulled all 15½" casing 5-10-38.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Parker Drilling Company,**

Address **302 Nat'l Bank of Tulsa Building**

Tulsa, Oklahoma.

By *John L. Taylor*
 Title **Drilling Sup't.**

CLUB NO. 8109130 ON BROOKLYN BRIDGE

7-10-52

1. 1974 *Journal of the American Medical Association* 230: 1000-1001

[illegible]

4/20/11 5:12 PM