## UNITED STA

COPY TO O. C. C.

Form Approved. Eudget Bureau No. 42-R1424

0.11.20		
DEPARTMENT OF	THE	INTERIOR
CEOLOGICAL	CHE	WEV

 I.C-	05	75	<u> </u>	 _

DEFAITMENT OF THE INTERIOR	1 _ 1 M = Y 2		
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME		
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir, Use Form 9–331–C for such proposals.)	7. UNIT AGREEMENT NAME		
reservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME		
1. oil sa gas	G. L. Erwin 'B' Fed. NCT-2		
well gas other	9. WELL NO.		
2. NAME OF OPERATOR	5		
Texaco Inc.	10. FIELD OR WILDCAT NAME		
3. ADDRESS OF OPERATOR	Justis North - (Montoya, Fusselman & Ellenbur 11. SEC., T., R., M., OR BLK. AND SURVEY CR		
P. C. Box 728, Hobbs, New Mexico 88240	11. SEC T R M ORRIK AND SURVEY OR		
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	AREA		
below.)	Sec. 35, T-24-S, R-37-E		
AT SURFACE: 330' FEL & 330' FSL	12. COUNTY OR PARISH 13. STATE		
AT TOP PROD. INTERVAL:	Lea New Mexico		
AT TOTAL DEPTH: Unit Letter 'P'	14. API NO.		
6. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE.	14. API NO.		
REPORT, OR OTHER DATA			
	15. ELEVATIONS (SHOW DF, KDB, AND WD)		
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	3159' (DF)		
TEST WATER SHUT-OFF			
RACTURE TREAT	Fig. 3.		
HGOT OR ACIDIZE	1		
EPAIR WELL	(NOTE: Report results of multiple completion of the		
PULL OR ALTER CASING .	change on Forth F-830) 4 1979		
MULTIPLE COMPLETE	(FD T. 1919)		
CHANGE ZONES	U. S. GEOLOGICAL SURVEY		
BANDON*  []  []  []  []  []  []  []  []  []  [	rger HOBBS, NEW MEXICO		
other) <u>Request Approval to aban</u> don Ellenbur Cone of Triple Downhole Commingle.	Ret		
7. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state	e all pertinent details, and give pertinent dates		
including estimated date of starting any proposed work. If well is d measured and true vertical depths for all markers and zones pertinen	irectionally drilled, give subsurface locations and at to this work.)*		
1. Rig up.			
2. Set CIBP in 2 7/8" Ellenburger	c Coa string @ 7160'		
Abandon Ellenburger.	. osg. string a proo .		
Abandon Ellenburger.			
O De 500 m. I a a a i l la ma Man l a	Observe to a 7 and and		
3. Pump 500 gals. acid down Monto	oya String to Clean up		
perforations 7050'-7060' & 71]	18'-7130'.		
4. Install production equipment.			
as downhole commingle of Monto	oya & Fusselman zones.		
~			
Case No. 5345	•		
Order No. R-4895 Subsurface Safety Valve: Manu. and Type	Set @ Ft.		
8. The eby certify that the foregoing is true and correct			
SIGNED / F C +-y3- TITLE ASST. Dist. SI	apt. page 2-13-79		
Tille The Tille	± DATE		

(This space for Federal or State office use)

APPROVED BY CONDITIONS OF APPROVAL, IF ANY:

TITLE

FEB 1 3 1979
ACTING DISTRICT ENGINEER