State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103

District Office		Transcale and I value	ar resources Department		Ę	om (*-105
DISTRICT I		OIL CONSERVATION DIVISION			Revi	sed 1-1-89
Pr>Box 1980, Hobbs, NM 85241-198	0					
DISTRICT II		2040 Pacheco St. Santa Fe, NN: 87535			NO.	
Pri Drawer DD, Artesia, NM 88210		Salla FE, N	V. 8 (3.13.		25-11375	
DISTRICT III				5 Indicate	Type of Lease	
1000 Rio Brazos Rd , Aztec, NM 874	10				STATE X FEE	
,	. •			6. State Cil	& Gas Lease No.	
SUNDRY NOTICES AND REPORTS ON WELLS				- managarin	B-1732	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A						
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"					une or Unit Agriement Name	
(FORM C-101) FOR SUCH PROPOSALS.)					5	
1 Type of Well		=			Ramsey State	
OIL _	GAS					
WELL X	L X WELL OTHER					
2. Name of Operator				8. Well No		
Primal Energy Corporation				a. Well No	•	
3 Address of Operator				9 Pool name or Wildcat		
211 Highland Cross, Suite #227, Houston, TX 77073				Langlie Mattix TRivers-Queen-Grayburg		
4 Well Location					Manux /Rivers-Queen-Ort.yburg	
Unit Letter K	1980 Feet From The	SLine and _	1980 Feet From The W	Line		
1						
Section 36	Township	24S Ras			Lea Com	it/
10 Elevation (Show whether DF, PKB, PT, GP, etc.)						
	Chools Amman	3137' RT				
NOTICE	OF INTENTION TO:	tate Box to Indicate	Nature of Notice, Report, or O			
HOTICE	OF HATEMATION TO:		SUBSE	EQUENT RE	EPORT OF:	
FERFORM REMEDIAL WORK	PLUG ANI	DABANDON X	REMEDIAL WORK			
	_	ــــــــــــــــــــــــــــــــــــــ	TONIDOTAL WORK		ALTERING CASING	
TEMPOPARILY ABANDON	CHANGE :	PLANS	COMMENCE DRILLING OPNS		PLUG & ABANDONMENT	
FULL OR ALTER CASING			CASING TEST & CEMENT JOB	П		
THE CO.						
10 Cusa-ha Parasada Glassia da			OTHER:			
wark) SEE RULE 1103	perations (Clearly state all pertinen	t details, and give pertinent.	dates, including estimated date of starting of	any proposed		
WIND SEE TRUSTEE TOO						
1. Set CIBP at 3350'. Spot 2	2600' Spot 25 or from 1	oad hole w/9.5 ppg r	nud.			
2. Spot 25 sx from 2700 to ;3. Spot 10 sx plug from 60'	to surface. Frest markon	ond along least	5 sx from 351' to 251'.			
fare on brag nom on	to surface. Effect marker	and clean location.				
_	_					
					•	
I hereby certify that the information abo	ove true and complete to the best	of my knowledge and belief				
SIGNATURE	Kunde					
77		TITLE Man:	iger, Operations and Engineering		ATE_11/8/01	
TYPE OR PRINT NAME Joh	n Abernethy			Tier	EDHONE NO. 201 021 222	
This space for State Use)				1151	EPHONE NO. 281-821-3600	====
APPROVED BY						
ONDITIONS OF APPROVAL IF AN		TITLE			.)ATE	
in the same of the	•					

