

DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

(Other instructions on reverse side)

Bureau No. 42-R1424

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

5. LEASE DESIGNATION AND SERIAL NO.

LC-032579(e)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Westates Federal

9. WELL NO.

4

10. FIELD AND POOL, OR WILDCAT

N. Justis Fusselman

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec 1, T-25-S, R-37-E

12. COUNTY OR PARISH

Lea

13. STATE

N. Mex.

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

National Coop. Refinery Assoc.

3. ADDRESS OF OPERATOR

2215 Wilco Building, Midland, Texas 79701

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)

At surface

SW/4, NW/4 Section 1, T-25-S, R-37-E
1980' FNL, 330' FWL of Section

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3138' KB

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Westates Federal No. 4 was plugged and abandoned 7-5-80 as follows:

- 1) Spotted 60 sx cement plug 6488'-6912'. (Fusselman perms. 6932'-7040')
Top cement plug tagged.
- 2) Loaded hole with 9.5# salt water gel mud. 5 1/2" casing parted at 3615'.
Pulled 3615' - 5 1/2" casing.
- 3) Spotted 100 sx cement plug at 3671'. No fill.
- 4) Spotted 100 sx cement plug at 3671'-3586'. Top cement plug tagged.
- 5) Spotted 80 sx cement plug at 3586'-3398'. (8 5/8" casing shoe @ 3450')
Top cement plug tagged.
- 6) Cut 8 5/8" casing @ 1040'. Could not pull casing.
- 7) Spotted 30 sx cement plug 1056'-1017'. Top cement plug tagged.
- 8) Cut 8 5/8" casing @ 814' and pulled casing.
- 9) Spotted 100 sx cement plug at 870'-737'. Top cement plug tagged.
- 10) Spotted 100 sx cement plug at 281'-148'. (13 3/8" casing shoe @ 234')
Top of cement plug tagged.
- 11) Spotted 15 sx cement plug at 0-15'.
- 12) Welded plate on casing and marked with a permanent marker.
P&A 7-5-80.

18. I hereby certify that the foregoing is true and correct

SIGNED

B. J. Hinson

TITLE Dist. Prod. Supt.

DATE 7-24-80

(This space for Federal or State office use)

APPROVED BY

(Orig. Sgd.) PETER W. CHESTER

TITLE ACTING DISTRICT ENGINEER

DATE JUN 28 1980

CONDITIONS OF APPROVAL, IF ANY:

JUN 5 1981