

Form 9-331
(May 1963)UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		5. LEASE DESIGNATION AND SERIAL NO. LC-032579(e)	
2. NAME OF OPERATOR National Coop. Refinery Assoc.		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
3. ADDRESS OF OPERATOR 2215 Wilco Building, Midland, Texas 79701		7. UNIT AGREEMENT NAME	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface SW/4 NW/4 Section 1, T-25-S, R-37-E 1980' FNL, 330' FWL of Section		8. FARM OR LEASE NAME Westates Federal	
14. PERMIT NO.		9. WELL NO. 4	
15. ELEVATIONS (Show whether DF, RT, GN, etc.) 3138' KB		10. FIELD AND POOL, OR WILDCAT N. Justis Fusselman	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 1, T-25-S, R-37-E	
		12. COUNTY OR PARISH Lea	13. STATE N. Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Westates Federal No. 4 is currently completed in the Fusselman 6932'-36', 6944'-46', 6971'-81', 7000'-06', 7010'-40'. Recently the tubing and packer were pulled, and the 5 1/2" casing was found to be collapsed at approx. 4828'. Attempts to repair the casing were unsuccessful. Additional work on the well is not warranted. Previous approval has been obtained from the USGS to recomplete Westates Federal No. 8 in the Fusselman as a replacement well for Well No. 4, and this workover will be done in the immediate future.

The proposed plugging procedure is as follows:

- 1) 50 sx cement plug 6500'-6900'. 4 1/2" hole. Plug Set 5-22-80
- 2) Cut off 5 1/2" casing @ approx 4800'.
- 3) 50 sx cement plug @ approx 4725'-4875' (5 1/2" casing stub).
- 4) 50 sx cement plug @ 3375'-3525' (8 5/8" casing shoe @ 3450').
- 5) Cut off 8 5/8" casing @ approx 2000'.
- 6) 75 sx cement plug @ approx 1950'-2050' (8 5/8" casing stub).
- 7) 75 sx cement plug @ 185'-285' (13 3/8" casing shoe @ 234').
- 8) 15 sx cement plug 0-15'.
- 9) Weld plate on casing and install marker.

RECEIVED

MAY 20 1980

U. S. GEOLOGICAL SURVEY
HOBBS, NEW MEXICORECEIVED
MAY 19 1980

18. I hereby certify that the foregoing is true and correct

SIGNED

B. J. Wilson

TITLE

Dist. Prod. Supt.

DATE

5-16-80

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE