

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE  
(Other instructions on reverse side)

Form approved,  
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC -032579 (e)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Westates Federal

9. WELL NO.

5

10. FIELD AND TOOL, OR WILDCAT

Justis Tubb Drinkard

Justis Blinebry

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

Sec. 1, T-25-S, R-37-E

1.

OIL WELL ☒ GAS WELL ☐ OTHER Oil - Oil Dual Completion

2. NAME OF OPERATOR

National Coop. Refinery Assoc.

3. ADDRESS OF OPERATOR

2215 Wilco Bldg., Midland, Texas 79701

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)

At surface

SW/4 NW/4 - Section 1, T-25-S, R-37-E

1730' FNL, 330' FWL of Section

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3140' DF

12. COUNTY OR PARISH

Lea

13. STATE

New Mexico

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☐  
☒  
☐  
☐

PULL OR ALTER CASING

☐  
☐  
☒  
☐

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON\*

REPAIR WELL

CHANGE PLANS

(Other)

Perforate

☒

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

☐  
☐  
☐

REPAIRING WELL

☐  
☐  
☐

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT\*

(Other)

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Westates Federal No. 5 is dually completed in the Drinkard (5958'-6020' Intermittent) and(Blinebry 5270'-5502' intermittent). The Drinkard is temporarily abandoned since it has reached its economic limit, and the Blinebry produces about 1.5 BO and 30 MCF per day.

The proposed workover is as follows:

1. Abandon Drinkard by setting a CI bridge plug at approximately 5900' with 10' cement on top of plug.
2. Plug off present Blinebry perfs 5270'-5502' by setting a CI bridge plug at approximately 5250' with 10' cement on top of plug.
3. Perforate Blinebry 5058', 5072', 5076', 5078', 5085', 5090', 5106', 5128', 5147', 5173', 5175', 5177', 5190', 5192', 5200', 5205', 5209', 5213', 5217', 5219', 5222', (21 holes).
4. Acidize with 2000 gals. and frac with 40,000 gals gelled brine and 60,000# sand.
5. Place well on production as single completion in Blinebry.

18. I hereby certify that the foregoing is true and correct

SIGNED

*[Signature]*

TITLE Dist. Prod. Supt.

DATE 7-12-73

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

APPROVED

DATE

13 1973  
ARTHUR R. BROWN  
DISTRICT ENGINEER

\*See Instructions on Reverse Side